AU-No	io 99 7	AIR (FORCE/I	NDUSTRY OBBS	REPAIR	ABLE P	OTTING	MATERIA	LS WOR	(SHOP, (• •	5
UNCLA	SSIFIED		-TR-81	-4113							NL		
	T of 3	₹											
		Ž,				with the statement. In respect to the statement of the st	There are a second seco	and the second			in	A Property of the Control of the Con	ts ts
				:									
											TO SERVICE		
1. N	The second							Pin S					
	`** /·	1	Şir.		A	(<u>egr</u>							

AFWAL-TR-81-4113



AIR FORCE/INDUSTRY REPAIRABLE POTTING MATERIALS WORKSHOP

BILL DOBBS

SYSTEMS ACQUISITION & SUPPORT BRANCH SYSTEMS SUPPORT DIVISION



NOVEMBER 1981

TECHNICAL REPORT AFWAL-TR-81-4113 Workshop Proceedings — 15 June 1981

" FILE COPY

Approved for public release; distribution unlimited

MATERIALS LABORATORY
AIR FORCE WRIGHT AERONAUTICAL LABORATORIES
AIR FORCE SYSTEMS COMMAND
WRIGHT-PATTERSON AIR FORCE BASE, OHIO 45433

 $\mathcal{A}_{C_{\mathbf{z}}}$

82 0² 16 007

NOTICE

When Government drawings, specifications, or other data are used for any purpose other than in connection with a definitely related Government procurement operation, the United States Government thereby incurs no responsibility nor any obligation whatsoever; and the fact that the government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data, is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture use, or sell any patented invention that may in any way be related thereto.

This report has been reviewed by the Office of Public Affairs (ASD/PA) and is releasable to the National Technical Information Service (NTIS). At NTIS, it will be available to the general public, including foreign nations.

This technical report has been reviewed and is approved for publication.

Project Engineer Systems Acquisition & Logistics Support Branch

Tech Mgr for Systems Acquisition Systems Acquisition & Logistics

Support Branch

Systems Support Division

FOR THE COMMANDER

Ronald H. Hand Chief, Systems Acquisition 6 Logistics Support Branch Systems Support Division

"If your address has changed, if you wish to be removed from our mailing list, or if the addressee is no longer employed by your organization please notifyAFWAL/MLS\$ W-PAFB, OH 45433 to help us maintain a current mailing list".

Copies of this report should not be returned unless return is required by security considerations, contractual obligations, or notice on a specific document.

AIR FORCE/56780/6 January 1982 - 180

INCLASSIFIED
SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

REPORT DOCUMENTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT HUMBER 2. GOVT ACCESSION NO	. 3. RECIPIENT'S CATALOG NUMBER
AFWAL-TR-81-4113 AN A110 997	7
4. TITLE (and Subtitle)	5. TYPE OF REPORT & PERIOD COVERED
Air Force/Industry Repairable Potting Materials Workshop	Workshop Proceedings
WOLKSHOP	15 June 1981 6. PERFORMING 03G, REPORT NUMBER
	N/A
7. AUTHOR(e)	B. CONTRACT OR GRANT NUMBER(4)
	1
Bill Dobbs	N/A
9. PERFORMING ORGANIZATION NAME AND ADDRESS	10. PROGRAM ELEMENT, PROJECT, TASK
Systems Acquisition & Logistics Support Branch	AREA & WORK UNIT NUMBERS
Systems Support Division, AFWAL/ML	P.E. 62102F
WrightPatterson AFB, OH 45433	24180704
11. CONTROLLING OFFICE NAME AND ADDRESS	November 1981
(same as 9)	Sentember 1981
	13. NUMBER OF PAGES 211
14. MONITORING AGENCY NAME & ADDRESS(If different from Controlling Office)	15. SECURITY CLASS. (of this report)
	1
Same	Unclassified
	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)	
to. Distriction statement to the report	
Approved for public release; distribution unlimit	ted.
17. DISTRIBUTION STATEMENT (of the abetract entered in Block 20, if different from	Penert)
17. DISTRIBUTION STATEMENT (of the abstract entered in block 29, it different no	ser staposty
Same	
•	
18. SUPPLEMENTARY NOTES	
None	
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)
Repairable Modules	
Materials	•
Manufacturing Processes	
- 	
20. ABSTRACT (Continue on reverse side if necessary and identify by block number)	
The ALCs reported that significant quantities of po discarded simply because it is impossible to repair	
that millions of dollars worth of electronic assemb	lies or subsecomblies are
condemned each year because of their inaccessibilit	y to repair. In situations
where the module may be de-potted there are too man	y different types of potting
materials and solvents involved. The Air Force has	been plagued for years with
steadily expanding quantities of potting materials	until there are presently
several hundred different stock listed compounds an	d solvents in the inventory.

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

20. The maintenance and storage of these solvents necessary for the removal of the different potting materials are very expensive.

The Repairable Potting Materials Workshop provided an information exchange between customers and manufacturers of potted electronic assemblies for airborne and ground based electronics. The results of this workshop indicate that the Air Force will definitely benefit from standardization of potting materials for electronic assemblies. The reduction in maintenance and condemnation costs will result in an Air Force cost savings of millions of dollars per year.

__

PREFACE

The Repairable Potting Materials Workshop was held in conjunction with the National Electronic Packaging and Production Conference (NEPCON East) June 15, 1981, at the New York City Coliseum, NY. The purpose of the workshop was to discuss the possibility of standardizing potting materials used on electronic assemblies for airborne and ground-base electronics. This area is of concern to the Air Force since many problems have been encountered when potted assemblies are improperly repaired. The results of two surveys, one with Industry and the other with Air Force Logistic Centers, were presented. The Industry survey was conducted by the University of Dayton Research Institute and the Air Force survey by ASD/RAOF. The ten member panel gave presentations and panel-audience discussions were held afterward.

NTIS GRA&I DTIC TAB Unannowneed Justification By Distribution/ Availability Codes Availability Codes Availability Codes	Access	ion Fo	r	
By	NTIS	GRA&I		X
By	DTIC T	AΒ	• [ו
By	Unanno	സംഗരമ്		\supset
Distribution/ Availability Codes Availability Codes Available Availability Codes Availability Codes	J ustif	icosu.		
Distribution/ Availability Codes Availability Codes Dist Special	D.,			
Aveil end/or Dist Special			/	
Dist Special	Avail	kariit	7 Cod	es
A		Avell .	ma/or	
A	Dist	მუიძმ	La l	
A		ļ		3-
Tic		-		
	TIC			
	TED			
CTED	/			

TABLE OF CONTENTS

Section		Page
I	INTRODUCTION	1
11	WORKSHOP PRESENTATIONS	3
	A. Introductory Remarks	3
	B. Needs and Requirements for Standardization of Potting Compounds	12
	C. SM-ALC Needs and Requirements for Potting Compounds	26
	D. OO-ALC Requirements for Repairable Potting Compounds	45
	E. Problems in Repairability of High Voltage Potted Assemblies	80
	F. Approaches to Standardization in Repair of Potted Electronic Assemblies	101
	G. Supplier's Philosophy of Repairability	109
	H. Embedment Material Selection Considerations for Repairability	124
	I. Repairable Potted High Voltage Assemblies	138
	J. Air Force Response to Survey	162
	K. Industry Response to Potting Compound Survey	185
111	CONCLUSION	207

SECTION I

INTRODUCTION

Recent meetings with government and industry personnel have highlighted the need for advancement and technology transfer in standardization and repair of potted electronic modules. AFWAL/MLSS has worked with PRAM and the ALCs in an attempt to reduce waste by standardizing potting materials and solvents for electronic modules. The ALCs have reported that significant quantities of potted electronic modules are discarded simply because it is impossible to repair them. The ALCs report that this results in a substantial loss to the government. Also, in the Air Force/Industry AD Manufacturing Cost Reduction Study, 4-6 March 1980, the Ordinance Panel identified several problems with potting materials on systems such as the Gator AP, Gator AT and Slufae. In most of these situations too many different types of materials are currently being used and a large portion of them cannot be depotted. Col. Parker, ASD/RA, 10 January 1980, said, "The Air Force has been plagued for years with steadily expanding quantities of potting materials until there are presently several hundred different stock listed compounds and solvents in the inventory to do basically the same job. Many of these compounds can't be removed from electronic components without damaging or destroying the component. Often the compound can't even be identified. Preliminary reports from the ALCs and other government agencies indicate millions of dollars worth of electronic assemblies or subassemblies may be condemned or damaged each year because of their inaccessibility to repair. Incidental to maintenance and condemnation cost may be losses due to decreased reliability and early component failure caused by the thermal or electrical properties of potting compounds."

Everyone agrees that no one potting material is adequate for every application but a large spectrum of applications could utilize a standardized repairable potting material. This spectrum of applications covered by the standardized potting material would include portions of all types of applications but probably in all cases it would not encompass the total application. This idea is depicted on the map on page 9. We believe that a program to standardize potting materials would save the Air Force millions of dollars per year.

SECTION II

WORKSHOP PRESENTATIONS

A. Introductory Remarks

Bill Dobbs AFWAL/MLSS WPAFB, OH 45433

REPAIRABLE POTTING MATERIALS MORKSHOP

· 是一次的原则,是是一种,这种种种的原则,是一种,是一种,是一种,是一种,是一种的原则,是一种的原则,是一种的原则,是一种的原则,是一种的原则,是一种的原则,是一种的原则,是一种的原则,是一种的原则

NATIONAL ELECTRONIC PACKAGING AND PRODUCTION CONFERENCE

15 JUNE 1981

NEW YORK CITY COLISEUM, NY

1. "MEEDS AND REQUIREMENTS FOR STANDARDIZATION OF POTTING COMPOUNDS"

GUS LANE WR-ALC/MAIES ROBINS AFB, GA 31098

- 2. "SM-ALC NEEDS AND REQUIREMENTS FOR POTTING COMPOUNDS"

 MIKE HARRIS

 SM-ALC/MAIPC

 NcCLELLAN AFB, CA 95652
- 3. "OO-ALC REQUIREMENTS FOR REPAIRABLE POTTING COMPOUNDS"

 MATHEW KELAIDIS

 OO-ALC/MACPA

 HILL AFB, UT 84056
- 4. "PROBLEMS IN REPAIRABILITY OF HIGH VOLTAGE POTTED ASSEMBLIES"

W. G. DUNBAR BOEING AEROSPACE CO. SEATTLE, WA 98124

5. "APPROACHES TO STANDARDIZATION IN REPAIR OF POTTED ELECTRONIC ASSEMBLIES"

CHARLES HARPER
WESTINGHOUSE ELECTRIC CORP.
BALTIMORE, MD 21203

6. "SUPPLIER'S PHILOSOPHY OF REPAIRABILITY"

MAC LARSEN
FURANE PRODUCTS DIV.
M & T CHEMICAL
LOS ANGELES, CA 90039

7. "EMBEDMENT MATERIAL SELECTION CONSIDERATIONS FOR REPAIRABILITY"

DALE SMITH HUGHES AIRCRAFT CO. FULLERTON, CA 92634

- 8. "REPAIRABLE POTTED HIGH VOLTAGE ASSEMBLIES"
 BOB SWENDSEN
 NORTHROP CORP.
 ROLLING MEADOWS, IL 60008
- 9. "AIR FORCE RESPONSE TO SURVEY"
 LT. GARY RAGSDALE
 ASD/RAOF
 WPAFB, OH 45433
- 10. "INDUSTRY RESPONSE TO POTTING COMPOUND SURVEY"

 JOHN ZIEGENHAGEN

UNIVERSITY OF DAYTON RESEARCH INSTITUTE 300 COLLEGE PARK DAYTON, OH 45469

OBJECT IVES


- PROVIDE INFORMATION EXCHANGE
- DISCUSS MAINTENANCE PROBLEMS
- DISCUSS REPAIR TECHNIQUES
- DISCUSS SURVEY RESULTS
- MAKE RECOMMENDATIONS ON A STANDARDIZED POTTING MATERIAL FOR ELECTRONIC MODULES

DEFINITION

THE TERMS


POTTING, EMBEDMENT, CASTING, ECAPSULATION & ENCASEMENT

ARE USED IN A BROAD SENSE TO INDICATE A THICK COATING OF MATERIAL OVER THE ELECTRONIC MODULE (THIS IS NOT INTENDED TO INCLUDE CONFORMAL COATINGS).



TWO MATERIALS SOLUTION

ENVIRONMENTAL REQUIREMENTS



QUEST 10NS

- WHAT REMOVAL TECHNIQUES ARE AVAILABLE FOR THE DIFFERENT POTTING MATERIALS?
- WHAT DESIGN CRITERIA SHOULD BE USED FOR REPAIRABILITY?
- WHAT AREAS SHOULD BE EXCLUDED FROM REPAIRABILITY?
- WHAT POTTING MATERIALS SHOULD BE USED FOR REPAIRABLE MODULES?

B. Needs and Requirements for Standardization of Potting Compounds

Gus Lane WR-ALC/MAIES Robins AFB, GA 31098

NEEDS AND REQUIREMENTS FOR STANDARDIZATION OF POTTING COMPOUNDS

ROBINS AIR FORCE BASE, GA

AVIONICS CENTER OF THE AIR FORCE

BRIEFER: GUS LANE WR-ALC / MAI

AIRBORNE ELECTRONICS DIVISION

PERSONNEL

2283

FACILITIES

480,948 SQ FT

SYSTEMS

318

LINE ITEMS

5,932

15,930

EQUIPMENT

192,79 UNITS (\$.96 BILLION)

FY-80 PRODUCTION

133,624 (THRU MAY) FY-81 PRODUCTION

FY-81 BUDGET

\$122 MILLION

93	7	100
2,918,293	220,314	3,138,607
MAIP BRANCH TOTAL	ATE BRANCH	GRAND TOTAL FOR FY-81

OUR BUSINESS — — AVIONICS

FY-81 WORKLOAD PROGRAMS

SECTIONS	MANHOURS	PERCENT
ELEC WARFARE	470,860	15
BOMB-NAV	523,876	17
RADAR-NAV	433,418	14
WEAPONS CONTROL	476,441	15
FIRE CONTROL	561,680	18
COMMUNICATIONS	452,018	14

いっかい からはいるなされていいないというできるというないというない

ELECTRONICS EQUIPMENT TYPICAL LIFE-CYCLE

1. DEVELOP TO SPEC

2. WE PROCURE:

X UNITS, WITH

Y SPARES, FOR Z YEARS

3. MOST EQUIPMENT EXCEEDS Z YEARS, WITH EXHAUSTION OF Y SPARES. MADE WORSE BY THROW-AWAY MODULES.

MANUFACTURING TECHNOLOGY FOR CONFORMAL COATING

FINAL REPORT: AFWAL-TR-80-4139

TWO COATINGS RECOMMENDED:

1. HUMISEAL 1B31 ACRYLIC

2. DOW CORNING DX-X9-6326 SILICONE

CONFORMAL COATINGS

POTTING COMPOUNDS

7.

1. ACRYLICS

- 2. EPOXIES
- 3. POLYSULFIDES
- 4. POLYURETHANES

4. POLYURETHANES

3. PARYLENE

5. SILICONES

5. SILICONES

2. EPOXIES

ELECTRONIC PRODUCTS JULY 1976

SILGAN ELASTOMERS:

- **CONFORMAL COATINGS, AND POTTING** 1. A NEW SYSTEM OF SEALANTS, COMPOUNDS.
- 2. CAN BE APPLIED BY BRUSHING, DIPPING, SPRAYING, OR POURING

3. QUESTION: ARE THEY SOLVENT REMOVEABLE ?

TO MEET THE MIL SPECS LET'S TRY:

1. SPRAY-ON COATING (THIN)

2. DIP COATING (UP TO 1 / 4 IN)

3. POUR OR FLOW (POTTING)

BUT USE THE SAME REWORKABLE MATERIAL

SUMMARY

- THE NEED FOR COATING AND POTTING **MIL-STD-202**
- 2. THE CONCEPT OF THROW-AWAY MODULES ID DEPRECATED
- NEED A STANDARD COATING AND POTTING MATERIAL THAT IS REMOVEABLE
- 4. MOST IMPORTANT:

SPECIFY THE STANDARD MATERIAL IN CONTRACTS

C. SM-ALC Needs and Requirements for Potting Compounds

Mike Harris SM-ALC/MAIPC McClellan AFB, CA 95652 REPAIRABLE POTTED ELECTRONIC ASSEMBLIES

The second secon

15 JUNE 1981

NEW YORK CITY, N. Y.

GOOD MORNING, I'M MIKE HARRIS FROM THE AIR LOGISTICS CENTER (ALC) AT MCCLELLAN AIR FORCE BASE, SACRAMENTO, CA. POTTED ELECTRONIC ASSEMBLIES AND SOLVENT REMOVERS HAVE BEEN AND STILL ARE MAJOR CONCERNS AND PROBLEMS AT SACRAMENTO.

BEFORE I GET INTO SOME AREAS OF CONCERN, I WILL GIVE YOU A BRIEF OVERVIEW OF HOW OUR SM-ALC, AND OTHERS, OPERATE. SACRAMENTO AIR LOGISTICS CENTER IS A DEPOT MAINTENANCE REPAIR CENTER.

THERE ARE SIX ALC REPAIR CENTERS IN THE U.S. PLUS AIR FORCE LOGISTICS CENTER HEADQUARTERS AT WRIGHT-PATTERSON AIR FORCE BASE, DAYTON, OHIO.

OKLAHOMA CITY ALC, OKLAHOMA; OGDEN ALC, UTAH; AND WARNER ROBINS ALC, GEORGIA; ALC IS THE SECOND LARGEST FACILITY IN NORTHERN CALIFORNIA AND SAN ANTONIO ALC, ARE THE LARGEST INDUSTRIAL FACILITIES IN THEIR RESPECTIVE STATES. SACRAMENTO ONE INTERESTING ASPECT OF THESE ALC'S IS THAT THEY ALL ARE CHARACTERIZED BY A DEGREE OF LARGENESS IN THEIR GEOGRAPHIC LOCATIONS. THREE INSTALLATIONS: TEXAS IS THE LARGEST EMPLOYER IN THE SOUTHWEST. SACRAMENTO ALC IS THE TECHNOLOGY REPAIR CENTER (TRC) FOR MANY VARIED AND COMPLEX EQUIPMENTS. EXAMPLES ARE:

AND THEIR VANS OR SHELTERS, HONEY COMB STRUCTURES, AND F/FB 111, A-10, FLIGHT CONTROL INSTRUMENTS, GROUND CONTROL APPROACH RADAR ELECTRONICS HYDRAULICS, GROUND COMMUNICATIONS ELECTRONICS, SURVIVAL RADIO, F-4 AND T-39 AIRCRAFT. AS YOU CAN SEE, MAINTENANCE IS OUR BUSINESS. OF 12,042 CIVILIAN EMPLOYEES AT MCCLELLAN, ALMOST HALF (49.5%) ARE IN MAINTENANCE.

IF YOU COMPARE THE AIR FORCE DEPOT MAINTENANCE OPERATIONS TO THE TOP 500 PRIVATE ENTERPRISES, OUR COST OF OPERATIONS, EXPRESSED IN SALES, WOULD PLACE US 164TH

IN COMPARISON TO NUMBERS OF EMPLOYEES, WE PLACE 130TH.

IN ORDER TO MAINTAIN A STATE OF READINESS, MEETING DEFENSE REQUIREMENTS, WE EXPENDED OVER 38 MILLION MANHOURS IN 1980 REPAIRING AIRCRAFT COMPONENTS, GROUND SUPPORT EQUIPMENT AND COMMUNICATIONS SYSTEMS.

こうしょう とうしょう おんしんと 日本のできる いんかんきょう まらがから カイラ はんかかき

HAVE NO OPERATING APPROPRIATIONS, (NO MONEY FROM UNCLE SAM - SO NO MONEY FROM OUR MAINTENANCE FACILITY OPERATES SIMILAR TO THAT OF A PRIVATE CONTRACTOR. US TAXPAYERS),

DEVELOPMENT OF AN OPERATING BUDGET. THIS BUDGET AND THE REPAIR PRICES REQUIRE MAINTENANCE DEVELOPS REPAIR PRICES, FOR VARIOUS END ITEMS, AS A RESULT OF THE OUR CUSTOMERS HAVE APPROPRIATIONS TO PAY FOR THEIR WORKLOAD REQUIREMENTS. LOCAL, COMMAND AND AIR FORCE APPROVAL. EARNED REVENUE, THRU COMPLETION OF JOB ORDERS, IS OUR MEANS OF PAYING THE BILLS.

IN FY 80 WE SOLD \$1,406,318,782 IN SERVICES.

SO WE HAD A PROFIT OF \$50,997,947 OR 3.6% OUR COSTS WERE \$L,355,320,781. OF SALES. OF COURSE, WE, LIKE YOU, HAVE OUR PROBLEMS WITH INFLATION.

INCREASED LEAD TIME FOR PRODUCTION DUE TO LACK OF PROPER REPLACEMENT PARTS AND MANAGEMENT, INCREASED PRODUCTIVITY, REPAIR SPECIALIZATION THRU IMPLEMENTATION OF UNIQUE TECHNOLOGY REPAIR CENTERS AND PLANT MODERNIZATION, THERE HAVE BEEN CONTINUING PRESSURES CAUSED BY HIGHER LABOR, MATERIAL AND UTILITY COSTS PLUS FOR EVERY GAIN IN EFFICIENCY AND COST REDUCTION WE'VE MADE WITH IMPROVED EXCESSIVE WORKLOAD REQUIREMENTS IN THE PRIVATE SECTOR.

COSTS TO OVER 110%, BUT OUR MAJOR INCREASE HAS BEEN IN UTILITIES WHERE WE'VE OUR LABOR COSTS PER HOUR HAVE INCREASED BY 134% SINCE 1970 AND OUR MATERIAL EXPERIENCED A 510% INCREASE. TWO AREAS WHERE YOU, THE PRIVATE CONTRACTOR, COULD HELP SLOW THIS INFLATION RATE ARE:

- 1. STANDARDIZE POTTING COMPOUNDS AND SOLVENT REMOVERS.
- 2. SIMPLIFY IDENTIFICATION OF COMPOUNDS AND SOLVENTS, POSSIBLY BY CODING THE PART THAT IS POTTED WITH USEFUL POTTING AND SOLVENT INFORMATION.

EFFECTIVE POTTING COMPOUND REMOVER SHOULD MEET THE FOLLOWING REQUIREMENTS: THE MAJOR DIFFICULTY, AS I SEE IT, IS A SUITABLE SOLVENT REMOVER. AN

- 1. DISINTEGRATE OR DISSOLVE ALL THE CURED POTTING RESINS BY CHEMICAL ACTION WITHIN AN ACCEPTABLE TIME.
- 2. BE NON-HAZARDOUS TO THE TECHNICIAN AND THE ENVIRONMENT.
- NOT CAUSE SWELLING OF THE POTTING MATERIAL WHICH WOULD DAMAGE PARTS. М.
- 4. NOT ATTACK OR DESTROY OTHER MATERIALS USED WITH AND AROUND THE COMPONENT BEING REPAIRED.

LABOR AND MATERIAL COSTS MAY NOT ESCALATE QUITE AS MUCH AS THEY HAVE IN THE THIS TO ME SOUNDS LIKE A TALL ORDER, BUT, IF THESE REQUIREMENTS CAN BE MET, PAST TEN YEARS.

ADVANCED TECHNOLOGY, BUT HOW MUCH EFFORT HAS GONE INTO DEVELOPING METHODS OF I KNOW MANY OF THESE PROBLEMS HAVE BEEN ADDRESSED WITH NEWER WORKLOADS AND REMOVAL FOR OLD TECHNOLOGY? WE ARE CONCERNED WITH GETTING TO THE ROOT OF THESE PROBLEMS, WHICH TAKES US BACK TO PROFITABILITY AND LONG-TERM BUSINESS STABILITY.

SYSTEM (DPS). UNDER DPS WE COULD CUT, OR AT LEAST STABILIZE, COSTS AND LEAD THE DEFENSE PRIORITIES ACT OF 1950, DOD ESTABLISHED THE DEFENSE PRIORITIES TIME THROUGH:

- MULTI-YEAR CONTRACTING (CAUSING HIGHER VOLUME ORDERS/SUPPORTING CAPITAL INVESTMENTS),
- INCREASED EMPHASIS TOWARDS MATERIAL RESEARCH AND DEVELOPMENT.
- DOD MANUFACTURING TECHNOLOGY PROGRAMS (MANTECH, ETC.), IMPROVING PRODUCTS, THEREFORE IMPROVING PRODUCTIVITY AND RESPONSIVENESS. ω.

WHY IS IT SO IMPORTANT THAT WE HAVE REPAIRABLE POTTING COMPOUNDS AND NON-DESTRUCTIVE SOLVENTS?

COMPETENCE TO SUPPORT AIR FORCE OPERATIONAL FORCES IN THE EVENT OF A GLOBAL THE PRIMARY FUNCTION OF THE ALC'S IS TO PROVIDE A READY SOURCE OF TECHNICAL CONFLICT AND DO IT COST-EFFECTIVELY.

The Part of the Pa

WE ARE NOT ABLE TO SATISFACTORILY PERFORM THIS FUNCTION WITHOUT THE HELP OF THE PRIVATE SECTOR. I RECALL HAVING A PROBLEM IN 1963 WITH ONE OF MY MICROWAVE TRANSMITTERS WHILE STATIONED AT MARCH FIELD NEAR RIVERSIDE, CA.

The second secon

SEALED CONTAINER. THE TECH ORDER WIRING DIAGRAM DID NOT STATE THE CONTENTS OF THIS CONTAINER, ONLY THAT IT WAS "TOP SECRET" AND WHERE TO SEND IT TO PURCHASE WITH A 12 VOLT LIGHT BULB. THE BULB HAD BURNED OUT. THIS WAS AN OBVIOUS AND AFTER MANY HOURS OF TROUBLE-SHOOTING WE FOUND OUR PROBLEM WAS IN A 2" X 2" MATERIAL. AFTER REMOVING THE MATERIAL, I FOUND A SMALL RESISTOR IN SERIES A REPLACEMENT. I BROKE THE SEAL AND INSIDE WAS A STYROFOAM-TYPE POTTING DELIBERATE ATTEMPT BY A CONTRACTOR TO SELL MORE SEALED CONTAINERS. GENTLEMEN, THIS IS NOT AN ISOLATED INCIDENT, IT NEITHER SUPPORTS OUR FUNCTION NOR PROTECTS THE BEST INTERESTS OF THE U.S.

The state of the s

SOLUTIONS TO OUR COMMON PROBLEMS. LIP SERVICE TO THE READINESS OF OUR COMBAT MAINTENANCE FACILITIES. IT IS IMPORTANT - NO, IMPERATIVE - THAT WE REACT TO THE LIMITATIONS THAT FACE US NOW AND CONTINUE TO GIVE SERIOUS ATTENTION TO THE PROBLEMS AND CONCERNS I DISCUSSED THIS MORNING EXIST NOW IN OUR DEPOT THESE SYMPTOMS AND APPLY THE NECESSARY EMPHASIS AND RESOURCES TO FIND FORCES LEADS TO DISASTER.

BEING SECOND IN THIS BUSINESS
IS BEING A
LOSER

), the ΔL^2 sequences for kepairable Potting compounds

Mathew Kelaidis 00-ALC/MACPA Hill AFB, UT 84056

۱<u>.</u> ۲.-

LOGISTICS CENTER OCDEN AIR



POTTING COMPOUND PRESENTATION

WORKSHOP ON

いきこうとう かいかい となる ときかない かままで かしょう もんがい しゅうき からいれる

REPAIRABLE POTTED ELECTRONIC ASSEMBLIES

15 JUNE 1981

PRESENTATION BY: MATHEW KELAIDIS PREPARED BY: CARLYLE JOHNSON









は、ことを教養のであっている。これでは、一般の教育を見るとは、教育などのでは、

INTRODUCTION

DIRECTORATE OF MAINTENANCE AT HILL AIR FORCE BASE, UTAH. MAINTENANCE ACTIVITIES COMPRISE A MAJOR PORTION OF THE AIR FORCE LOGISTICS COMMAND'S SUPPORT EFFORTS. WE IN MAINTENANCE BELIEVE THAT ORGANIZATIONS LIKE OURS ARE THE DRIVING FORCE OF GOOD MC ING, I AM MATHEW KELAIDIS FROM THE OGDEN AIR LOGISTICS CENTER'S THAT LOGISTICS SUPPORT.

DIRECTORATE'S ANNUAL OPERATING BUDGET IS 242 MILLION DOLLARS WHILE OUR EQUIPMENT AND FACILITIES REPRESENT AN INVESTMENT OF ALMOST 250 MILLION. OVER 19,000 PEOPLE, OUR MAINTENANCE DIRECTORATE IS THE LARGEST ON-BASE ORGANIZATION WITH APPROXIMATELY 6,000 PEOPLE OR 48 PERCENT OF THE 13,000 TOTAL OTITITAN WORKFORF AND AN ANNIAL PAYROLL OF 145 MILLION DOLLARS. THE AT OGDEN, WHICH IS THE LARGEST SINGLE EMPLOYER IN THE STATE OF UTAH WITH

ABOUT ONE-THIRD OR 283 OF THESE BUILDINGS BELONG TO THE MAINTENANCE COMPLEX HERE AND AT THE UTAH TEST AND TRAINING RANGE ON THE WESTERN SHORE OF THE GREAT SALT THERE ARE 843 BUILDINGS WITHIN THE 6,600 ACRES THAT MAKE UP HILL AIR FORCE BASE:

INCLUDE THE MINUTEMAN, TITAN, MAVERICK, SRAM, MX, FALCON AND SIDEWINDER SYSTEMS; AND THE MANY SUBSYSTEMS ("BLACK BOXES AND INSTRUMENTS) FROM SEVERAL WHERE WE ARE RESPONSIBLE FOR THE F-4, AND THE F-16; SEVERAL MISSILES WHICH OUR PRODUCTION EFFORTS ARE BROKEN DOWN INTO THREE MAJOR CATEGORIES:

WORKLOAD IS ACCOMPLISHED IN OUR 450,000 SQUARE FOOT HANGAR COMPLEX WHERE THE AIRCRAFT UNDERGO TOTAL REPAIR AND MODIFICATION. MOST OF THE AIRCRAFT OUR FIRST PRODUCT DIVISION IS THE AIRCRAFT DIVISION.

N

ASSORTED ELECTRONIC REPAIR SHOPS ARE LOCATED. THESE WORKLOADS OCCUPY EIGHT BAYS WHICH CONTAIN A TOTAL OF 181, 780 SQUARE FEET. IT IS IN THIS AREA THAT THE MAJORITY OF THE POTTING AND DEPOTTING OPERATIONS ARE ENCOUNTERED. UNITS AND TRAINING DEVICES. THIS IS BLDG 100 WHERE THE AIRCRAFT, MISSILES AND THE MISSILE AND AIRCRAFT SYSTEMS DIVISION OVERHAULS AND MAINTAINS THE MISSILE SYSTEMS PREVIOUSLY MENTIONED AS WELL AS NAVIGATION INSTRUMENTS, PHOTOGRAPHIC

INVOLVE SOME POTTING AND ENCAPSULATION REQUIREMENTS BUT NOT TO THE EXTENT OF SOME OF THE OTHER SYSTEMS SUCH AS AIM-9 SIDEWINDER MISSILES AND AIRCRAFT. THIS IS BLDG 5 WHICH HOUSES THE SRAM AND MAVERICK MISSILE ELECTRONIC AND HYDRAULIC REPAIR SHOPS AND THE TRAINING DEVICES REPAIR SHOP.

ALL OF THESE WORKLOADS INVOLVE NUMEROUS TYPES OF ENCAPSULATION AND POTTING PROCEDURES AND PROBLEMS. IN THIS PRESENTATION, WE WOULD LIKE TO DISCUSS BRIEFLY THE FOLLOWING POINTS WHICH ARE AN INTEGRAL PART OF THE POTTING CONCEPT AND EFFORT.

SYSTEM MAINTAINABILITY

EXCESSIVE ADDITIONAL COSTS 0 0 00

FUTURE PROCUREMENT

RECOMMENDATIONS

POINTS OF DISCUSSION


- SYSTEM MAINTAINABILITY
- EXCESSIVE ADDITIONAL COSTS
 - FUTURE PROCUREMENT
- RECOMMENDATIONS

SYSTEM MAINTAINABILITY

SYSTEM MAINTAINABILITY

- NON REPAIRABLE HARD CASED POTTIMG
- NON AVAILABILITY OF ASSETS
- PROPRIETARY RIGHTS
- CONTROL MONITORING





SYSTEM MAINTAINABILITY

これできるとことでは、ないとはないからいではないかられていると

CEHTAINLY WE REALIZE THAT IN MANY INSTANCES POTTING IS VERY NECESSARY TO PREVENT DAMAGE FROM VIBRATION, HEAT AND MOISTURE AND IT IS NOT OUR INTENTION TO IMPLY WORKSHOPS AS A COMBINED EFFORT WITH THE VENDORS AND USERS WE CAN ELIMINATE OF THE PROBLEMS WHICH ARE ASSOCIATED WITH POTTING AND DEPOTTING OPERATIONS THAT ALL POTTING IS BAD OR UNNECESSARY. IT IS HOPED THAT THROUGH THESE

THE CONTRACTOR GOES OUT OF BUSINESS OR DECIDES TO DISCONTINUE PRODUCTION OF THE MUST BE THROWN AWAY DUE TO THE FAILURE OF A VERY INEXPENSIVE INTERNAL COMPONENT WE ARE SEEING AN INCREASE IN POTTED MODULES ENCASED IN HARD COMPOUNDS AND SOME RUBBER AND SILICONE BASED COMPOUNDS WHICH ARE EXTREMELY DIFFICULT AND IN SOME SUCH AS A DIODE OR TRANSISTOR. THIS IS NOT ECONOMICALLY SOUND IN ITSELF AND FREQUENTLY PUTS US IN A PRECARIOUS POSITION. THAT BEING, IF AT A FUTURE DATE CASES IMPOSSIBLE TO REMOVE. IN MOST OF THESE INSTANCES, AN EXPENSIVE MODULE ITEMS, THEN WE HAVE NO WAY OF REPAIRING THE MODULES.

ASTRONOMICAL AND OFTEN PROHIBITIVE, CONSEQUENTLY, WE ARE FORCED TO REPAIR ITEMS AS WE HAVE EXPERIENCED MANY TIMES IN THE PAST, CONTRACTORS DO NOT RESPOND TO ORGINALLY PROJECTED LIFE. MANY OF THOSE FLYING OR REPAIRING WEAPON SYSTEMS ARE AWARE, MANY WEAPON SYSTEMS HAVE BEEN EXTENDED CONSIDERABLY BEYON THEIR IF PER CHANCE SOME DO INTENDED FOR THROW AWAY TO MAINTAIN THE OPERATION OF THE WEAPON SYSTEM. RESPOND, RETOOLING AND SMALL PRODUCTION RUNS MAKE COSTS AND LEAD TIMES TODAY ARE YOUNGER THAN THE WEAPONS WITH WHICH THEY ARE WORKING. SOLICITATIONS TO PROVIDE OUT-OF-PRODUCTION ITEMS.

ANOTHER FACTOR WHICH HINDERS PROCUREMENT OF ALTERNATE VENDORS IS THE PROPRIETARY RIGHTS RESERVED BY THE ORIGINAL VENDOR.

ENCAPSULATION, SIGNIFICANT JUSTIFICATION SHOULD BE PROVIDED TO WARRANT THE USE \$1200.00 AND TWO AT AN ESTIMATED COST OF \$2700.00. WHEN NEW SYSTEMS ARE BEING DESIGNED WHICH INCORPORATE NON REPAIRABLE COMPONENTS DUE TO THE USE OF HARD THE SYSTEM REQUIRES THREE MODULES, ONE AT AN ESTIMATED COST OF THE NEW SIDEWINDER "L" CONFIGURATION HAS BEEN DESIGNED TO USE THROW AWAY OF NON REPAIRABLE ITEMS. MODULES.

ATTENTION SHOULD BE DIRECTED IN NEW SYSTEM DESIGN REQUIREMENTS TO LIMIT THIS IN THE FUTURE.

というで している とうしょう とうしゅう かんしゅう ないがら ないない ないしゅうしゅう

EXCESSIVE ADDITIONAL COSTS

こうこうかい うちゅう とうかんとう まままない いままはい かしまる ましめい つなりませいかん

POTTED COMPONENT EXPENSES

FACILITY CHANGES

REMOVAL SOLVENTS & CHEMICALS

POTTING COMPOUNDS

• IMCREASED LABOR STANDARDS

AIM - 9 POTTING COSTS

たいこうけんでは、これではないとなっていまでは、ままではないできます。 でいっていましましている

LABOR HOUR COST

1.5 HRS FOR REMOVAL/APPLICATION

\$15,352 HOURLY LABOR RATE

800 MISSILES REPAIRED PER QTR

\$73,689,60 COMPUTATION: 1.5 x \$15.352 = 23,028 x 800 = \$18,422.00 x 4 QTRS =

REHOVAL SOLVENT COST

4500 GALLOMS PER YEAR OF SISULFA-SOL 3 \$9,00 PER GAL.

COMPUTATION: $4500 \times $9.00 =$

40,500,00

POTTING COMPOUND COST

1 POTTING KIT REQUIRED PER DAY @ \$378,00

AVERAGE 20 DAY MONTH


COMPUTATION: $\$378.00 \times 20 = \$7,560.00 \text{ PER MO} \times 12 = -$


TOTAL PER YEAR


\$204,909,00

90,720,00





















EXCESSIVE ADDITIONAL COSTS

あるとこかが、子をはいかと

EXAMPLE OF HOW MUCH MONEY IS INVOLVED IN POTTED COMPONENT REPAIR COMPARED WITH NONPOTTED COMPONENTS, WE WOULD LIKE TO PRESENT THE FOLLOWING INFORMATION FOR IT IS A WELL-KNOWN FACT THAT POTTED COMPONENTS REQUIRE MUCH MORE TIME AND EXPENSE TO REPAIR THAN NONPOTTED COMPONENTS. IN THESE DAYS OF INCREASING AUSTERITY, WE MUST DILLIGENTLY SEEK WAYS TO DECREASE REPAIR COSTS. AS AN CONSIDERATION.

REPAIR/OVERHAUL OF THE AIM-9 SIDEWINDER MISSILE REPAIRED AT OGDEN ALC. THESE FIGURES APPLY TO THE POTTING AND DEPOTTING COSTS CONCERNING

COMPCALAR ON THIS ONE REPAIR AREA, IT COSTS ALMOST A QUARTER MILLION DOLLARS PER LAL FOR REMOVAL AND APPLICATION OF THE POTTING. THESE FIGURES DO NOT INCLUDE THE COST OF THE FACILITY AND SPECIAL EQUIPMENT WHICH WOULD MAKE THE COST IT CATTES SEEN FROM THESE FIGURES HOW EXPENSIVE IT IS TO DEAL WITH POTTED CONSIDERABLY HIGHER.

IN MOST CASES WHEN POTTED COMPONENTS ARE WORKED, IT INDUCES ADDITIONAL COST FOR FACILITY CHANGES, REMOVAL CHEMICALS AND SOLVENTS, POTTING COMPOUNDS AND INCREASED LABOR STANDARDS.

THESE ARE ALSO THE HIDDEN COSTS OF SHIPPING, STORAGE AND HANDLING OF THE CHEMICALS AND COMPOUNDS WHICH ADD TO END ITEM REPAIR COSTS.

THIS EXAMPLE I HAVE PRESENTED IS ONLY ONE OF HUNDREDS OF ITEMS WHICH INVOLVE SIMILAR POTTING PROBLEMS SO IT IS EVIDENT THAT MILLIONS OF DOLLARS PER YEAR ARE SPENT ON THE POTTING EFFORT. WHENEVER POTTED COMPONENTS ARE USED, SUFFICIENT BENEFITS SUCH AS REDUCED FAILURE RATE, EXTENDED OPERATING LIFE AND IMPROVED PERFORMANCE SHOULD BE OBTAINED TO PROVIDE A SAVINGS TO OFFSET HIGHER PROCUREMENT

N

A CONCERTED EFFORT SHOULD BE MADE TO RESTRICT USE OF HARD POTTING COMPOUND TO JUSTIFIED APPLICATIONS. FUTURE PROCUREMENT

PROCURENT IN THE FUTURE

- RESTRICTION OF CERTAIN TYPES OF MATERIALS.
- MANUFACTURERS PROVIDE REMOVAL METHODS & MATERIALS REQUIRED,
- * POTTING BE USED ONLY WHEN ABSOLUTELY NECESSARY,
- UTILIZATION OF ENVIRONMENTAL CONNECTORS,

FUTURE PROCUREMENT

EXISTENCE AND BEING REPAIRED AT THE PRESENT BUT THE "LESSONS LEARNED" NOW SHOULD THERE IS VERY LITTLE THAT CAN BE DONE WITH THE ITEMS WHICH ARE ALREADY IN INFLUENCE GREATLY WHAT HAPPENS IN THE FUTURE.

SOME OF THE THINGS WHICH WE FEEL SHOULD BE CONSIDERED ARE AS FOLLOWS:

CERTAIN MATERIALS WHICH ARE DIFFICULT OR IMPOSSIBLE TO REMOVE SHOULD BE RESTRICTED FROM USE UNLESS IT IS DETERMINED TO BE ABSOLUTELY NECESSARY AND UNAVOIDABLE. 2. WHEN POTTED ITEMS ARE PROCURED THE MANUFACTURER SHOULD PROVIDE A REMOVAL METHOD AND IDENTIFY MATERIALS REQUIRED SO THAT INDIVIDUAL REPAIR SHOPS WILL NOT REQUIRE SPECIAL ASSISTANCE FROM THEIR CHEMICAL LABORATORY PEOPLE.

CONCERTED EFFORT SHOULD BE MADE TO ELIMINATE ALL POTTING THAT IS NOT ABSOLUTELY ESSENTIAL. AS WAS INDICATED PREVIOUSLY, A

4. INCREASED EFFORT SHOULD BE MADE TO UTILIZE ENVIRONMENTAL CONNECTORS ON AIRCHAFT AND MISSILE SYSTEMS RATHER THAN POTTED CONNECTORS.

RECOMMENDATIONS

RECOMMENDATIONS

- SIGNIFICANTLY DECREASE POTTING AND DEPOTTING COSTS AND ELIMINATE MUCH OF THE CONFUSION OF ORDERING, DISTRIBUTION, HANDLING AND USE WHICH AFFLICTS WE STRONGLY RECOMMEND STANDARDIZATION OF POTTING MATERIALS WHICH SHOULD US NOW. o
- WE FEEL THAT CHEMICAL REMOVAL METHODS ARE MORE ADVANTAGEOUS FOR OUR REQUIRE-MENTS THAN WOULD BE MECHANICAL REMOVAL. 0
- COMPOUNDS SHOULD BE OF A TYPE THAT DO NOT REQUIRE HARSH OR ABUSIVE SOLVENTS THAT DAMAGE COMPONENTS, WIRING OR PRINTED CIRCUIT RUNS. o
- POTTING COMPOUNDS SHOULD BE OF A TYPE THAT IS EASILY AND QUICKLY REMOVED. 0
- COMPOUNDS SHOULD BE EASILY APPLIED AND CURE TIME SHOULD BE RELATIVELY FAST. 0
- COMPOUNDS SHOULD BE TRANSPARENT TO ALLOW PRE-TEARDOWN INSPECTION BEFORE STRIPPING. 0
- THAT SOME TYPE OF ENFORCEMENT SHOULD BE AS WAS MENTIONED BEFORE WE ALSO FEEL THAT SOMINMPLEMENTED TO ELIMINATE UNNECESSARY POTTING. o
- OTHER METHODS SUCH AS VACUUM PACKING COULD BE CONSIDERED RATHER THAN POTTING. O

RECOMMENDATION

S

- o STRONGLY RECOMMEND STANDARDIZATION.
- O CHEMICAL REMOVAL OF POTTING BE USED.
- o SHOULD NOT REQUIRE HARSH OR ABRASIVE CHEMICALS.
- o COMPOUNDS BE EASILY & QUICKLY REMOVED.
- o COMPOUNDS SHOULD BE EASILY APPLIED,
- o CURE TIME SHOULD BE FAST.
- o SHOULD BE TRANSPARENT.
- o ELIMINATE UNNECESSARY POTTING.
- o ALTERNATE METHODS TO POTTING SHOULD BE DEVELOPED.

E. Problems in Repairability of High Voltage Potted Assemblies

> W. G. Dunbar Boeing Aerospace Co. Seattle, WA 98124

PROBLEMS AND GUIDELINES
FOR REPAIRABILITY OF
POTTED HV POWER SUPPLIES

W. G. DUNBAR JUNE 15, 1981 BOEING AEROSPACE COMPANY



PROBLEM AREAS AND SUGGESTED SOLUTIONS

High-voltage systems are plagued with annoyances that are unnoticed in low-voltage systems. Some of the more subtle annoyances are described in the following paragraphs:

<u>Debris</u>. Small dielectric flakes or chips lodged or lying on the surface or edge of a coil will align themselves with the electric field. They will be charged to the same potential as the surface to which they are attached, acting as a point on the surface. This will decrease the utilization factor of the encapsulating gas or oil and cause excessive corona and eventual breakdown. Inspections and thorough cleaning with high-pressure air will eliminate this problem.

Small pieces of insulation must be cleaned out of transformer cases, otherwise "chips" may lodge in the field between a coil and metal and cause corona, which ruins the gas or oil insulation. Wire terminations should be designed and installed so that the field approaches that of a parallel-plate configuration without point discontinuities.

Mechanical Stress. Sharp edges or points on fasteners, connections, and rivets can cause insulation boards to chip or crack. Terminations should be designed to minimize mechanical stress points on the insulating boards. This can be accomplished by molding the terminal in a solid insulating material that is attached to the board. The metal spacers not only reduce the mechanical stress but also increase the surface utilization factor between the flange edges.

Flexible Wiring. Flexible wiring is easily misaligned during the potting process, causing high voltage wires to be overstressed during operation. High-voltage, extra-flexible wiring is acceptable in some limited cases. It should be used only as a last resort. When used, it should be guided from terminal to terminal to eliminate the probability of the wire insulation intermittently touching other surfaces containing higher or lower voltage circuits.

Manufacturing Cleanliness. The need for manufacturing cleanliness cannot be overstressed. Gloved hands should be mandatory when papers, films, and other cleaned surfaces are handled. Small amounts of oils or acids can cause an improper bond or encapsulation. Any paper, cloth, film, or other dielectric material is suspect and should be inspected by material, shop fabrication, and engineering personnel. Smoke-emitting objects in materials fabrication shops may contaminate the dielectric.

Mold Release Agents. Silicone products may contaminate certain epoxies, urethanes, and other insulating materials. Compatibility and contamination of materials for bonding purposes should be investigated prior to fabrication. When there is an incompatibility, precautions must be taken to avoid contamination.

<u>Testing</u>. Flaws in outer surfaces or between a single conductor and a surface in a clear material can be visually inspected. When a coil, circuit, or multiple-conductor assembly is tested, the test must include the detection of imperfections between coil layers, circuit parts, and assembly layers. This implies that the total assembly must be energized in such a way that all overstressed electrical parts will be detected. An overvoltage test and/or overfrequency test are two methods for testing.

Environment and Life. Most high-voltage circuits and parts will be installed in enclosed pressurized containers. This reduces the probability of thermal shock, but not temperature extremes. Testing an insulation in a small dish is inadequate. Fabricated parts and circuits should be assembled (per specification) inside the packaging container and tested through the temperature extremes with all circuits energized. Five to nine cycles are recommended. Pre-environmental tests and post-environmental tests should include corona, dissipation factor, insulation resistance, and a visual inspection of breaks, tears, and deformation. Any significant change in appearance or electrical characteristics are reasons for further testing and/or modification prior to qualification and life testing.

<u>Tabs</u>. Small tabs often are placed on wires and parts for identification and installation purposes. When these coils and circuits are encapsulated, filmtape tabs such as Mylar adhesive may cause built-in gas pockets or voids. These voids may initiate partial discharges and eventual voltage breakdown. If tabs are required, they should be made of porous materials that are compatible with and easily wetted by the encapsulant.

<u>Spacers</u>. Spacers between the two energized encapsulated units must be nearly void-free and have smooth or rounded surfaces to reduce tracking susceptibility across the spacer surface. The spacer surface should be designed as though the voltage at the dielectric surfaces was from base electrodes, not dielectrics.

<u>Coatings</u>. Coated metal surfaces have higher breakdown voltage characteristics than uncoated surfaces, provided the correct coating material is applied. Some coatings do not blend well, flake, and reduce the electrical stress capability of





Figure 1. Common Boundary, HV and LV Circuits



とうこう という からからてきない しんきゅう あんしゅう あんしゅう かんしゅう

Figure 2. Direct Current Breakdown Voltage Between Parallel Plates

the two electrodes. Others may have pin holes and voids or blisters that also cause flaking. Coatings must be evaluated under identical environmental and electrical stress conditions to be fully qualified.

Determining Corona Limitation Voltage. The corona initiation voltage (CIV) of an electrical apparatus can be determined when the design parameters and the applicable Paschen-law curve are known. The Paschen curve used depends on the type of gas in which the corona would occur, the temperature of the gas, and the configuration of the electrodes. Figure 2 compares Paschen curves for different gases under d.c. voltage. The most common gas is air. If the temperature exceeds 260°C , special Paschen curves must be used.

DESIGN IDEAS THAT HAVE WORKED IN HIGH-VOLTAGE EQUIPMENT

Examples of successful designs used to decrease field stress in high-voltage equipment are described in the following paragraphs:

Terminal Boards and Supports. Composite and laminated insulation is used for terminal boards and for supports that separate the colls and wiring from the cores, structure, and containers. A terminal board for high potential should be made from qualified insulation. The board may be flat, if the voltage is less than 20 kV, provided the electrical stress is:

- o Less than 20 V/mil for long life (10 to 30 years)
- o Less than 20 to 50 V/mil for short life (1 month to 1 year)

With treated boards in a dry, clean atmosphere of pure gas, these values can be doubled.

Terminal boards operating at voltages greater than 20 kV should be contoured to increase the creepage paths. Three basic methods of contouring (shown in fig. 3) are:

- Cutting slots (gas-filled regions) between the terminals
- o Building barrier strips between the terminals
- o Mounting the terminals on insulated standoffs

Combinations of the three methods may be necessary for voltages greater than $100 \, \text{kV}$.

The slots in a slotted circuit board form creepage paths as well as flashover barriers on both sides of the board. A board with barriers is the most difficult to design. The barriers must be built on both sides of the board, and the board has to be made from materials that will not form creepage paths under the barriers, inside laminated boards, or through the board laminates. The barriers also must not interfere with the terminals or the wiring.

Insulated standoffs are a form of barrier strips. The standoffs are difficult to design because they must withstand the forces applied by the terminals, and the terminal anchor must be embedded in the top surface of the standoff. The anchor must be contoured for minimum electrical stress.




Figure 3. Terminal Boards

High-Voltage Leads. Leads between high-voltage parts should be made of round, smooth-surfaced, polished metal tubing. Steel and nickel-plated metals are preferred, but softer metals often are used because they are easier to fabricate. The radius of curvature on all bends should be at least 2.5 times the conductor diameter to avoid flattening or crushing the tube at the bend. The ends of the tubes should be flattened as little as possible, but this becomes difficult for pieces other than straight sections. When the end of the tubing is flattened, the corona-suppression shield should extend over the edges and the flattened end of the tubing, as shown in figure 4. Ample space must be provided between the inside surface of the insulator and the metal tube. A safe design would be based on the assumption that the full voltage stress exists on the top edge of the bushing.

Hollow tubing must be vented. Vent holes should be drilled through one wall of the tubing at both ends. The vent hole should face the corona shield.

<u>Special Design Features</u>. High-voltage, flexible-lead terminations should be designed to eliminate pressure points on the terminal board (fig. 5); pressurpoints will cause delamination, which enhances internal tracking. The terminal should be protected with a corona ball or shield.

Other insulation techniques include either burnishing or enameling over the knots in ties to prevent the feathered ends from becoming points from which corona discharges will emanate (fig 6).

<u>Standoffs and Boards</u>. For high-density packaging, high-voltage parts are separated by either laying them out on the surface of a board or placing them on

AIR FORCE WRIGHT AERONAUTICAL LABS WRIGHT-PATTERSON AFB OH F/6 5/1 AIR FORCE/INDUSTRY REPAIRABLE POTTING MATERIALS WORKSHOP, (U) AD-A110 997 NOV 81 B DOBBS AFWAL-TR-81-4113 NL UNCLASSIFIED 2 or 3 * : Ģ






Figure 4. High Voltage Lead and Bushing




IMPROPER



PROPER

Figure 5. High Voltage Terminals






Figure 6. High Voltage Ties

standoffs. A few critical problem areas on board delamination, joints, cleanliness, surface coating, and edges.

<u>Board Delamination</u>. Boards used to separate high-voltage parts from grounds must serve a dual purpose: structural and mechanical. Fiberglass usually is used as the major composition of boards, with epoxy or other material used for the filler. When the board is made in large, thick sections, the filler material occasionally does not completely penetrate the fiber. This will cause the board to have large internal voids that are difficult to detect.

Once a board is found with this type of fault, it is best to have all boards scanned for defects, otherwise application of a high potential will initiate internal tracking and failure. These types of failures usually are discovered in the field after many hours of service.

Joints. Screws frequently are used to join a metal plate to the end of a rod or standoff. This is strictly unacceptable in high-voltage designs because the screw hole is deeper than the screw; thus, a void exists at the bottom of the screw hole and the screw will attain a potential causing a very high field gradient at the point of the screw and along the threads. This will cause a high-voltage gradient across the air gap. Then partial discharges will enhance treeing through the standoff, resulting in arcing. Banding with a loose-fitting clamp is best. A tight-fitting clamp should not be used because if the clamp is tightened enough to secure the standoff in place, it will cause the standoff to delaminate, and tracking will occur (see fig. 7).

<u>Cleanliness and Surface Coatings</u>. Prior to coating the surface of a board or joint, before or after assembly, the surface must be thoroughly cleaned of oils,




Figure 7. Board Standoff Clamping

greases, dirt, foreign objects, cleaning salts, and acid deposits. Large boards often require two or more cleaning processes . Following cleaning, the board should be taken to the area where the coating is applied. During transportation the board should not be touched with bare hands or contaminated objects, nor exposed to a contaminating atmosphere. The coating must be placed on the board in a dust-free/lint-free compartment. Likewise, during installation into the final assembly, the board must be handled so as not to contaminate the surface.

Edges. A large board often has cutouts, holes, slots, and indentations.

Remember, all edges are to be smoothed and rounded. A sharp edge on an insulating board has the same effect as a sharp edge on a metal sheet.

Taps and Piates. A high-voltage rectifier normally is assembled from a series of connected diodes, and occasionally, a voltage tap is required at the center of the diode string. This tap should be made of material having the same diameter as the diode surface and thick enough for attachment of a round tubular connection. Soldered joints should not be used because most solder electrodes have lower breakdown potentials than metals such as steel, nickel, brass, copper, and aluminum.

A potential shaping surface within the stack of series-connected diodes can be a thin plate of metal provided with a large-radius edge. This curved edge suppresses corona.

GUIDELINES TO MINIMIZE FAILURES

A CONTRACTOR

LAYOUT TO MINIMIZE AVERAGE VOLTAGE STRESS

DESIGN TO PROVIDE ADEQUATE SPACING

-) USE CREEPAGE BARRIERS
- b) INCREASE PACKAGE SIZE IF NECESSARY
- :) SELECT HIGHER STRENGTH DIELECTRIC

RESTRAIN ROUTED WIRES TO PREVENT MOVEMENT DURING POTTING

PARTS AND MATERIALS SELECTION TO MINIMIZE VOLTAGE STRESS INTENSIFICATION

-) SOLDER BALLS
- SELECT HARDWARE TO AVOID EXPOSED SHARP EDGES
-) USE VOLTAGE SHIELDS
- d) USE LARGE DIAMETER SMOOTH CONDUCTORS
- SELECT INSULATION WITH COMPATIBLE DIELECTRIC STRENGTH (AC) **6**
- SELECT INSULATION WITH COMPATIBLE RESTIVITY (DC)

GUIDELINES TO MINIMIZE FAILURES (CONTINUED)

The second of th

DESIGN TO LIMIT MODULE TEMPERATURE RISE

- USE RELIABILITY (DERATING) CRITERIA TO DETERMINE ACCEPTABLE COMPONENT TEMPERATURES, o
- LAYOUT TO MINIMIZE THERMAL PATH FROM HEAT SOURCES TO HE FINK,
- CONSIDER USE OF "LOADER" (HIGHER CONDUCTIVITY) INSULATING MATERIAL.
 - d) CONSIDER USE OF METAL OR CERAMIC THERMAL SPREADERS.
- CONSIDER USE OF FINS OR INTERFACE MATERIAL TO REDUCE THERMAL RESISTANCE FOR MODULE TO AMBIENT.
- .) IF NECESSARY INCREASE PACKAGE SIZE.
-) SELECT THERMALLY STABLE MATERIALS

DESIGN TO MINIMIZE NUMBER AND SIZE OF VOIDS IN INSULATION

- d) PACKAGING GEOMETRY TO ALLOW "EASY FILL" AND GAS ESCAPE,
- b) DESIGN PACKAGE TO ACCOMMODATE CURE SHRINKAGE.
- c) SELECT LOW VISCOSITY, LONG POT LIFE MATERIAL.

GUIDELINES TO MINIMIZE FAILURES (CONTINUED)

日本 日本 大大

DESIGN TO PREVENT INSULATING MATERIAL CRACKS AND DELAMINATION, AND PART OR SOLDER JOINT FAILURE, DURING THERMAL CYCLING.

- PACKAGING CONFIGURATION TO ACCOMMODATE INSULATION SHRINKAGE AND EXPANSION (PHYSICAL CONSTRAINTS).
- b) MAXIMIZE COEFFICIENT OF EXPANSION COMPATIBILITY.
- c) MAXIMIZE MATERIAL COMPATIBILITY TO PROMOTE ADHESION.
- SELECT LOW BULK MODULUS INSULATION IF MATERIAL IS SEVERELY CONSTRAINED. Q
- e) COMPONENT MOUNTING TO PROVIDE STRESS RELIEF.
- IF NECESSARY SOFT CONFORMAL COATING OF SENSITIVE COMPONENTS. ()

DESIGN TO MINIMIZE PARTICULATE CONTAMINATION

PACKAGING DESIGN TO ALLOW EASY CLEANING (NO "PARTICLE TRAPS").

DEISGN TO MINIMIZE UNDESIRED CIRCUIT INTERACTION (COUPLING)

- LAYOUT TO SEPARATE LOW NOISE SENSITIVE CIRCUITS FROM NOISY CIRCUITS.
- b) IF NECESSARY USE SHIELDING.

MAXIMUM PER MIL-HOBK 251 HEAT SINK 1000 CONDUCTION COOLED MODULE TEMPERATURE RISE UNIFORM DISSIPATION AND CONDUCTIVITY y for K = 0.015 (IN) POTTED --MODULE y for K = 0.005 (IN) x (IN3 °C) FIGURE 8. 200 90. .25-20 .05-5 -02-~ (WATTS) ~ . 0 어>

大七月五日本

F. Approaches to Standardization in Repair of Potted Electronic Assemblies

Charles Harper Westinghouse Electric Corp. Baltimore, MD 21203 ROLES OF STANDARDIZATION OF REPAIR OF POTTED ASSEMBLIES

• STANDARDIZATION IN DESIGN AND APPLICATION

• STANDARDIZATION IN MATERIALS PERFORMANCE REQUIREMENTS

• STANDARDIZATION FO MATERIALS REPAIR TECHNIQUES

STANDARDIZATION IN DESIGN AND APPLICATION

- FUNCTIONAL PARTITIONING (ELECTRICAL REQUIREMENTS, OTHER REQUIREMENTS)
- ▶ APPLICATION PARTITIONING (COST, MANUFACTURABILITY, ETC.)
- CRITICAL COMPONENT PARTITIONING
- THROW-AWAY VS. NON-THROM-AWAY CONSIDERATIONS

STANDARDIZATION IN MATERIALS PERFORMANCE REQUIREMENTS

● LOW VOLTAGE, REPAIRABLE

· LOW VOLTAGE, NON-REPAIRABLE

· HIGH VOLTAGE, REPAIRABLE

O HIGH VOLTAGE, NON-REPAIRABLE

· LOW LOSS, REPAIRABLE

● LOW LOSS, NON-REPAIRABLE

• OTHER PERFORMANCE REQUIREMENTS

STANDARDIZATION OF MATERIALS REPAIR TECHNIQUES

• STANDARD IDENTIFICATION TECHNIQUES

• STANDARD CHEMICAL STRIPPING

→ STANDARD MECHANICAL REPAIR

TABLE I

QUANTITATIVE REQUIREMENTS FOR QUALIFICATION TESTS

Value	(2)	465-485		5.0	4.6		.003	.004			1 x 10 ¹⁴	1 x 10 t 2			45	75	10% Reduction from	individual pro-	ducts		190	190
ASTM or Fed-Std-406	5011	4031	4021			4021				4041			ASTM D2240							4011 ASTM D495		
Method Paragraph	4.6.2	4.6.3								4.6.5			4.6.5							4.6.6		
Units		Volts/Mil (Min)		Maximum	Maximum		Maximum	Maximum		ohm-cm	Minimum	Minimum		Minimum			Maximum			Seconds	Minimum	Minimum
Property	Specific Gravity (1)	Dielectric Strength, 1/8 inch	Dielectric Constant	Type I at 10 ³ Hz	Type II at 10 ³ Hz	Dissipation Factor	Type I at 10 ³ Hz	Type II at 10 ³ Hz	Hydrolytic Stability	Volume Resistivity	Type I Before Conditioning	Type II Before Conditioning	Hardness	As Received	Type 1	Type II	After Conditioning	Type I	Type II	Arc and Track Resistance	Type 1	Type 11

TABLE I (Continued)

		Method	ASTM or	
Property	Units	Paragraph	Fed-Std-406	Value
Thermal Expansion	Cm/cm/ _O C	4.6.7	2031	,
Type 1	Maximum			280×10^{-6}
Type II	Maximum			$^{20} \times 10^{-6}$
Thermal Conductivity	$Cal/sec/cm^2/^0C/cin$	4.6.8	ASTM C-177	
Type I	Minimum			6×10^{-4}
Type 11	Minimum			15×10^{-4}
Thermal Weight Loss	Percent	4.6.9	7041	
Type I	Maximum			3.70
Type II	Maximum			0.42
Thermal Shock Resistance	Cycles (Min)	4.6.10		5
Flammability		4.6.11	2021	
Thermal Vacuum Weight Loss	Percent	4.6.12	ASTM E-595	
Type I	Maximum			1.0
Type II	Maximum			1.0
Condensables	Percent	4.6.12	ASTM E-595	
Type I	Maximum			0.25
Type II	Maximum			0.1
Water Absorption	Percent	4.6.13	7031	
Type I	Maximum			0.05%
Type II	Maximum			0.05%
Viscosity and (Pot Life)	CPS, Maximum	4.6.14	ASTM 0-2393	
Type I	(Hrs., Minimum)			20,000 (2)
Type 11				4,000 (2)

G. Supplier's Philosophy of Repairability

Mac Larsen
Furane Products Div.
M&T Chemical
Los Angeles, CA 90039

REPAIRABILITY:

A MATERIALS SUPPLIER'S VIEWPOINT

Mac Larsen

Furane Products M&T Chemical Co. 5121 San Fernando Rd. W L.A.,Ca 90039

Page 1

When considering the idea of repairability, several contradictions come to mind.

- 1) Many electrical applications require plastics that must withstand service temperatures in excess of 200°C. and potentials of over 50,000 volts. When one has a need to repair a malfunctioning device encapsulated with such a material, he soon finds out just how tough this kind of plastic can be.
- 2) The ever increasing delicacy of electronic devices such as glass diodes, semiconductors with bonded gold wires, or stress sensitive coils, require tough, highly filled plastics to protect them and attempts to cut into such an encapsulated circuit may cause more damage and take longer than the repair is worth.
- 3) When plastic is designed to be humidity resistant, ozone resistant, and insoluble in organic solvents, it also is going to be very impervious to most chemicals used as strippers.

So what is the plastics engineer supposed to tell a distraught electronics engineer when he finds that 400 circuitboards were assembled with the wrong parts and that the new tough heat and chemical resistant plastic everyone was so proud of has just hardened to a 95 Durometer D? The answer can be very involved. This may be an exaggeration, but it does illustrate the point that repair cannot be an afterthought of design. As the prices and availability of specialized parts become more and more of a concern, or the importance of failure analysis to trouble shoot becomes evident, the engineer must begin to consider how the protective embedment material can be removed upon demand. One can search for a specialized

process to remove the plastic. He can also design the final part with an easily removable material with the possibility of sacrificing some quality or reliability. Understanding techniques, plastics and design for repairable items is becoming an important facet of the electronics industry. The plastics engineer has much to offer this field because he understands the chemical's impact on ultimate performance. This paper is intended to help the electronics design engineer understand the reasons for material removal, describe some established techniques, and offer some new techniques to ease the task of plastic removal.

Some of the more prevalent reasons for justifying removal or repair of electrical/ electronic devices are:

Replacement of defective part
Molding flaws
Failure Analysis
Calibration/Recalibration
Recovery

Replacement (or repair)

This type of repair requires a fairly accurate diagnosis of where the malfunctioning portion is located. In most cases, it is not feasible or desirable
to remove all of the coating or encapsulant in order to remove and replace only
one part. One would like to go directly to the part, replace it, and refill
the void with the same material or possibly a specially designed repair material.
This process may be a field repair where time and equipment are at a minimum,
and certainly the environmental problems can pose a particular problem such as
in the repair of underground telephone cables. In this case, original materials

must be easily removed and a field pack of the repair material, such as a soft urethane, must be insensitive enough to cold and moisture so it will transform from the liquid state into a soft rubber, once mixed and poured onto the cable repair area.

2) Process Flaws

Whether or not there is a significant production volume, there will always be a statistical relationship of good parts to rejected parts. The ability to correct flaws occurring in molding or coating processes, for instance, may be the area that makes or breaks a profitable item. In the case of flexible cable molding, the mold is treated with a release agent which allows the final cured part to be easily removed from the cavity. It is possible to incompletely cover the cavity with the release agent, causing the cable to adhere and rip as it is pulled away. Since much time has already been spent in the setup of the wires, etc., it becomes economically feasible to repair this portion. The most practical repair technique is to use the same material in a fresh mix, put the cable back into the mold, and pour the material in. In some cases it is necessary to clean the surface of the cable with a solvent and/or abrade the surrounding surfaces with fine emery cloth before filling with fresh material, so the freshly hardened material will adhere to the previously molded area.

3) Failure Analysis

And just as important is the technique used to dissect the faulty device for inspection. For instance, semi-conductor devices are put through tremendous stresses during molding processes, and if they malfunction there is reason to believe that inspection could shed some light on how to better design the part or process.

To analyze such a device, it is important that a delicate technique must be used so as not to incur additional damage. A widely used technique used here is to drop red fuming Nitric Acid onto the plastic and allow to soften or degrade the surface which can then be rinsed with acetone. Several cycles of this process will expose the chip without harming the lead frame or chip. The Nitric Acid must be very low in moisture in order to prevent it from reacting with and destroying the metallic components within the molded package.

4) Calibration

A little forethought here always helps. A device such as a trim pot, used in many circuits, must be exposed in order to be adjusted. Naturally, the easiest technique is to cover it with a soft material then encapsulate the entire circuit. When adjustment becomes necessary, one needs only to drill through the encapsulating plastic, then remove the soft covering and calibrate. Some suggestions for removable materials are: a high temperature wax, soft staking compound such as silicone or urethane, or possibly a small piece of zinc chromate tape. These are either soft or thermal plastic materials which, depending on the electrical requirements, can remain with the device or be removed. The wax can be melted out, while the soft polymers or tapes can be cut and removed.

5) Recovery

This reason for embedment removal justifies the most destructive type of process.

Although recovery of precious metals or parts is strictly speaking, not a repair item, it is valuable when parts are needed immediately but have an intolerable delivery time. Any type of removal technique can be used, providing that the sought after item can withstand it.

All of the examples given above can be catagorized into one of three techniques of plastic removal.

Thermal

Mechanical

Chemical

Just about any way one can think of to remove plastic will fall into one of these three classifications. Indeed, some techniques involve two or even all three of these groups. What is important to remember, however, is that the more stringent the requirements of the plastic, the more difficult the task is to remove or repair it.

As repair becomes more important, there are certain sacrifices that must be made in performance and reliability and/or cost of production in order to satisfy the repairability parameters. Some property considerations that should be thought of in the design of either a repairable or non-repairable device are listed below. (Materials are listed in increasing difficulty to repair).

<u>Material</u>	<u>Advantages</u>	<u>Disadvantages</u>
Thermoset Gel	Re-enterable	No support - Environmental
(Silicone Gel)	Extreme ease of removal	Resistance low; high cost
Soft Thermoplastic	Easily melted or cut	Low solvent resistance
(Urethane, Polyethylene)	with hot knife	Low service temperatures
Soft Thermoset	Moderate ease in cutting	
(Silicone, Urethane)	Good electricals possible	High cost - Silicones
Hard Thermoplastic (Polyimides, PPS)	Can be dissolved at high	Processing scale up;expensive
(roly illitues, rrs)	temp; good electricals	Temp required to melt too
		high for practicality
Hard Thermoset	Excellent electricals	Very difficult to dissolve,
(Epoxies, Phenolics)	High temp service Good environmental resistance	break, or melt

î Ş A technique that was investigated for the purpose of this paper involves Binary system encapsulation. What this process tries to do, is obtain the best of two worlds. That is mold a soft, repairable material directly around the repairable device then over encapsulate with a hard thermoset material, thus protecting the more vulnerable inner material against the effects of humidity, abrasion and shock. Upon the event of a repair, the hard outer casting can be opened up by mechanical means such as sawing to expose the easily cut soft polyurethane. Figure 1 shows a cast part and a cross sectioned piece to illustrate the construction. A total of four types of castings were made:

	<u>Inner (</u>	Casting	<u>Outer Casting</u>						
A)	Unfilled polyurethane	(Durometer 60A)	Unfilled o	ероху	(Durometer 8	15D)			
B)	Filled polyurethane	**	11	H	**				
C)	Unfilled polyurethane	n .	Filled epo	оху	19				
D)	Filled polyurethane	n	11	11	u				

The reason for filling is to adjust the thermal expansion rates to minimize internal stresses that may produce cracks. This concept is already used widely in potting processes, whereby a fluid potting material is poured into a thermoplastic case. In this example, unless the filling port is hermetically sealed, the soft repairable inner material would be subjected to possible harsh environments such as humidity, ozone, acids, or nitrous oxides. By overcasting with a thermoset as described above, a hermetically sealed package is automatic with the only openings or areas of possible contamination being wires or connectors. With proper planning regarding mechanical design, a hermetically sealed re-enterable system is possible. Figure 2 shows the effect of thermal cycling. After 3 cycles of -55 to 100^{OC} ., cracks appear in the unfilled epoxy but none in the filled version.

こうしている こうしょう こうしょう こうしゅうしゅう かんしん

Finally, to demonstrate the actual repairability of the system, Figure 3 shows a cut casting which exposes the urethane inner material. A razor blade, or perhaps a soldering iron with a knife edge, can be utilized to slice the polyurethane away. Figure 4 shows another clear soft durometer polyurethane that a hot instrument can readily penetrate thus enabling the technician to remove large chunks to expose faulty devices. Certainly this concept can be investigated to a much greater degree; however, internal design of electrical/electronic parts is such an important consideration of the package in its entirety, that one would have to design an epoxy/urethane system to match the requirements.

There has been much research into chemical means of removing plastics. Much has been written on the subject with entire product lines being built on a variety of strippers. As mentioned before, many electrical/electronic applications require thermally stable solvent resistant thermosets to adequately protect sensitive circuits. In most cases, a non-repairable material is one with these properties, and although it provides the best reliability it seldom affords itself to repair.

The concept most widely used to remove plastics, particularly thermosets, is to break apart or digest the polymer so it becomes more soluble. These chemicals can become very specific to generic types of polymers such as anhydride cured epoxies, silicones, etc. Once the chemistry is known, the selection of proper strippers is somewhat edisonian in practice. Generally, the thicker the cross sectional area, the harder it is to remove. Mechanical means of burning, sawing, or cutting off heavy layers can be used in conjunction with chemical methods. This is all labor intensive and so the reasons for repair become more and more critical to cost.

In deciding what kind of chemicals and methods to use to remove plastics there are several considerations to be taken.

- 1) Will the chemical be selective enough to stop dissolving when critical parts are uncovered?
- 2) Will any residual contaminants, such as acids, harm metal contacts or wiring even after the repair job is finished?
- 3) Are the chemicals toxic? Can they be readily disposed?
- 4) Will refluxing or other potentially expensive equipment be required?

Table I gives some idea of the variety of chemicals that are used to remove plastics. Unfortunately, in most cases, their performance does not outweigh their toxicity. There are combinations that have proven to be useful such as the following formula developed by G. R. Sprengling, Westinghouse R & D, and published in February, 1980 issue of Insulation Circuits.

50% Tall Pitch

25% b Napthol

25% Triethene Glycol

According to Sprengling, this "standard stripper" was found effective in dissolving all common insulating thermosets in a time of 1-6 hours @ 250°C. This exemplifies the supposition that there does exist combinations of chemicals that when mixed together will reverse the polymerization process resulting in the removal of plastics.

A proprietary mixture of non-corrosive chemicals was made for this paper to illustrate the reverse polymerization process and demonstrate selectivity of a stripper for various plastics. The items chosen for illustration were epoxy dip-coated hybrid circuits and polyurethane encapsulated cable connectors.

Page 9

The setup was oversimplified for purpose of illustration. A 500 ml Beaker was placed on a hot plate, filled 1/2 full with the stripping solution, heated to 70°C and was kept agitated by a Teflon coated magnetic strirrer which, by the way, was unharmed after hours of stirring. A round bottom distilling flask was filled with ice water to act as a refluxer. When fumes contact the cold flask, they condense and drip back into the beaker. A refluxing column could have been used; however, it would have made removal of parts more difficult for picture sequencing. Figure 5 shows before and after circuits with the small piles of undissolved resin above each board. Notice that some of the components on the right board are damaged from the solvent. The coatings used on these particular devices are similar to the circuit coating so the solvent could not be selective. Everything else on both boards, however, remain untouched, including the metal leads and copper cladding. An interesting observation here was that epoxy molded devices are virtually untouched by this stripper as well as epoxy/glass printed circuit boards.

The second set of figures show the removal of a polyurethane encapsulant from around a molded cable. Again, notice the before and after devices (Figure 6) and how the metal is still shiney, the wire insulation is intact and the termination (Diallyl Phthalate) piece is untouched. An important point to make is that the cable can now be repaired (re: soldering, adjusting of possible shorts, etc.) and that no additional damage was done to the actual electrical connections.

Many other repair techniques are used in the electrical/electronics industry and they are becoming more and more commonplace. Certainly the fact that it is possible to design a device with a removable embedment material just supports the expectations that plastics will continue to enjoy the paralleling high rate of growth with electronics. And it is becoming more and more evident that a close relationship must continue between electrical and plastics engineers in order to meet the ever increasing demands.

TABLE I EXAMPLES OF STRIPPERS

Acetic Acid

Formic Acid

Nitric Acid

Sulfuric Acid

Pheno1

Sodium Hydroxide

Ammonium Hydroxide

Di Butyl Amine

MDA

Tall Pitch

Naptho1

1, 4 Butane Diol

Tri Ethylene Glycol

Methylene Chloride

Perchloroethylene

Methyl Ethyl Ketone

M-Pyrol

Dimethyl Formamide

Phthalic Anhydride




FIG 1





FIG 3



FIG 4




FIG 5




FIG 6

URETHANE MOLDED CABLE



OMEMICALLY STRIPPED URETHANE MOLDED




FIG 6

H. Embedment Material Selection Considerations for Repairability

Dale Smith Hughes Aircraft Co. Fullerton, CA 92634 HUGHES

The second second

The state of the s

SELECTION OF EMBEDMENT MATERIALS AND DESIGN FACTORS

FOR THE REPAIRABILITY/REWORKABILITY OF ELECTRONIC MODULES

O. DALE SMITH

JUNE 15, 1981

HUGHES

INTRODUCTION

WHERE WE ARE TODAY

HISTORICAL BACKGROUND

EMBEDMENT MATERIAL

A POLYMERIC PACKAGE THAT ENCLOSES ELECTRICAL OR ELECTRONIC

HARDWARE THEREBY PROVIDING PHYSICAL AND ENVIRONMENTAL

PROTECTION

EMBEDMENT MATERIAL

BOTH REPAIR AND REWORK OPEPATIONS REQUIRE THE REMOVAL OF AN

EMBEDMENT MATERIAL. THIS EMBEDMENT MATERIAL MAY BE EITHER

A COATING, POTTING OR ENCAPSULATING COMPOUND WHICH IS

POLYMERIC IN NATURE.

the state of the s

REPAIR

THE ACT OF RESTORING DAMAGED ELECTRICAL OR ELECTRONIC

HARDWARE TO A NORMAL OPERATING CONDITION WITHOUT

SACKIFICING ITS INTENDED PERFORMANCE CHARACTERISTICS.

REWORK

THE ACT OF REVISING ELECTRICAL OR ELECTRONIC HARDWARE TO

NEWER DESIGN CRITERIA OF PERFORMANCE CHARACTERISTIC

WHICH IS GENERALLY MINOR IN NATURE.

HUGHES

NEED FOR REPAIR

REFURBISHMENT

COMPONENT FAILURE

STATIC DISCHARGE DAMAGE

IM-PROCESS SOLVENT DAMAGE

TEMPERATURE SENSITIVITY

CIRCUITRY FAILURE

WORKMANSHIP DEFECTS

LATENT DEFECTS

NEED FOR REWORK

MODIFICATION

PART SUBSTITUTION

UPGRADE FOR NEWER CAPABILITIES

REPAIR AND REWORK BENEFITS

SUBSTANTIAL COST SAVINGS

SALVAGE OF IRREPLACABLE PARTS/HARDWARE

PRECIOUS METAL RECLAMATION

NEED FOR REPAIR

REFURBISHMENT

COMPONENT FAILURE

STATIC DISCHARGE DAMAGE

IN-PROCESS SOLVENT DAMAGE

TEMPERATURE SENSITIVITY

CIRCUITRY FAILURE

WORKMANSHIP DEFECTS

LATENT DEFECTS

NEED FOR REWORK

MODIFICATION

PART SUBSTITUTION

• UPGRADE FOR NEWER CAPABILITIES

WHY NOT TOTAL PART REPLACEMENT?

- UNAVAILABILITY OF DISCONTINUED PARTS
- LONG LEAD TIME FOR SYSTEM READINESS
- EASE OF REPAIRABILITY
- LOWER COST

TRADITIONAL TYPES OF REMOVAL

CHEMICAL

• MECHANICAL

OTHER

SELECTION OF EMBEDMENT MATERIALS BASED ON:

PHYSICAL PROPERTIES

CHEMICAL RESISTANCE

ELECTRICAL CHARACTERISTICS

TYPES OF EMBEDMENT MATERIALS

ACRYLIC

POLYURETHANE

SILICONE

EPOXY

POLYSULFIDE

FLUOROSILICONE

POLYIMIDE

PARYLENE

FACTORS TO CONSIDER FOR ELECTRONIC MODULE EMREDMENT REPAIRABILITY

PROPER MATERIAL SELECTION

- USE OF GENERICALLY DIFFERENT MATERIALS
- USE OF HEAT CURE MATERIALS ADJACENT TO ROOM CURE MATERIALS
- USE OF BARRIER COATINGS

PROPER DESIGN

- ACCESSIBILITY OF TROUBLESOME HARDWARE

CHOICE OF COMPONENTS COMPATIBLE WITH THE FIELD ENVIRONMENT

- AVOIDANCE OF HIGHLY DENSE CIRCUITRY DESIGNS
- USE OF STANDARDIZED COMPONENT/HARDWARE

I. Repairable Potted High Voltage Assemblies

Bob Swendsen Northrop Corp. Rolling Measows, IL 60008

OF OF POTTED HIGH VOLTAGE ASSEMBLIES

1 200

R. SWENDSEN

NORTHROP Northrop Corporation Defense Systems Division

156-027942-003

GENERAL DESIGN CONSIDERATIONS


The second secon


● MATERIAL SELECTION

REPAIR TECHNIQUES

PLUG-IN HIGH VOLTAGE MODULES


- REPAIRABILITY
- MAINTAINABILITY
- MANUFACTURABILITY
- REL ÎABILITY/LIFE
- HEAT TRANSFER
- SIZE AND WEIGHT
- ♣ LIFE CYCLE COST






HIGH VOLTAGE MODULATOR

MODULATOR MOLD




POTTED H.V. MODULATOR






HV MODULATOR UNDER REPAIR








ER REPAIR HV MODULAT







MODULAR H.V. ASSEMBLY

HELIX TRIM REGULATOR PROTECT BUARE CAPACITOR ASSETTED HELIX TRIM REGULATOR BOARD COLLECTOR ARC DETECT BOARD CHASSIS/HEAT SINK ASSENBLY BLEEDER RESISTOR BOARD FRELAY BLOCK ASSEMBLY

H.V. MODULE-ASSEMBLY STAGES



CONNECTOR CONFIGURATIONS




3. TYPICAL CALINOFICAL CONNECT & NOW _ NED










PLUG IN MODULE CONNECTOR









J. Air Force Response to Survey

Lt. Gary Ragsdale ASD/RAOF WPAFB, OH 45433



ALC SURVEY ON

STANDARDIZATION OF POTTING COMPOUNDS AND SOLVENTS





TOTAL NUMBER OF SURVEY RESPONSES BY ORGANIZATION

21	-	9	15	4	2	6	က	61
AEROSPACE GUIDANCE & METROLOGY CENTER	EGLIN AFB	OKLAHOMA CITY ALC	OGDEN ALC	SAN ANTONIO ALC	SACRAMENTO ALC	WARNER ROBBINS ALC	WRIGHT-PATTERSON AFB	TOTAL RESPONSES



DO YOU USE POTTING COMPOUNDS ON YOUR JOB?

YES - 33

NO - 31


52%



DO YOU PRESENTLY REPAIR ANY POTTED ELECTRONIC COMPONENTS?

ES - 21

NO · 43 67%



WHICH TYPE OF RESPONSIBILITY DO COMPONENT USE/OR FOR POTTING YOU HAVE FOR ELECTRONIC COMPOUNDS?

REPAIR - 24 MANAGEMENT - 17 TECHNICAL - 29

34%

24%



PREVENTING ECONOMICAL REPAIR OF COMPOUNDS USED IN ELECTRONIC **EXPENDABLE AT DEPOT OR FIELD** EQUIPMENT PRESENTLY CODED MAINTENANCE ARE A FACTOR DO YOU FEEL THAT POTTING EVEL?

YES - 48

NO · 10

83%




DO YOU BELIEVE THAT THERE IS A NEED FOR A POTTING COMPOUND FOR ELECTRONIC MODULES THAT WILL PERMIT REPAIR OF THE FAILED **ELECTRONICS?**

YES - 53

NO · 5

91%



THESE ARE SOME EXAMPLES OF ELECTRONIC MODULES THAT ARE BEING THROWN AWAY BECAUSE DEPOTTING IS IMPOSSIBLE.

TYPE OF MODULE	#/MONTH	#/MONTH UNIT COST
TITAN MODULES	1.2	\$10K - \$38K
GI-T1-B GYRO	25	\$800.
AF AMPLIFIER	009	\$40 \$55.
MK-6 CONTROL BOX	8/YEAR	\$25K
		\$100K PER MONTH

\$1.2M PER YEAR



THESE ARE SOME OF THE SPECIAL REQUIREMENTS FOR THE ELECTRONIC MODULES THAT ARE BEING DISCARDED BECAUSE THEY CAN'T BE DEPOTTED.

HIGH VOLTAGE (3000V)

HIGH SHOCK (100Kg's)

VIBRATION

HIGH TEMPERATURE





SHOULD POTTING MATERIALS BE TRANSPARENT?

YES - 47 84%

8 · 0N

16%

REASONS:

PRO - VISUAL INSPECTION FOR FAULTS AID IN LOCATING FAILED COMPONENT MINIMIZE FURTHER DAMAGE WHEN DEPOTTING

CON CONCENTRATED LIGHT MAY AFFECT SOME ALLOW PROBING FOR TEST PURPOSES FILLERS ADD DESIRABLE PROPERTIES MICRO-COMPONENTS



PROLIFERATION PROBLEM IN THE AIR FORCE WITH POTTING COMPOUNDS USED IN ELECTRONIC REPAIR? DO YOU SEE EVIDENCE OF A

YES - 29

NO · 19

40%

%09



DO YOU THINK POTTING COMPOUNDS ARE APPLIED IN AREAS WHERE THEY ARE UNNECESSARY?

YES - 15 NO - 35

%02

30%

EXAMPLE: ENCAPSULANTS TO PREVENT COMPONENT VIBRATION ON REPAIRABLE MODULES WHERE HUMIDITY IS NOT A PROBLEM

MASSIVE POTTING WHERE A FILM TYPE WILL DO

ELECTRONIC MODULES HOUSED IN HERMETICALLY SEALED/GAS FILLED CASES



REPAIR, DUE TO THE MYRIAD OF POTTING COMPOUND FORMULATIONS? IS THERE ANY TIME LOST DURING AIRCRAFT/MODULE

NO - 12

YES · 27

%69

31%

COMMENTS: PROPORTIONAL TO NUMBER OF

COMPOUNDS

DEPENDS ON SET-UP TIME

DEPENDS ON SUPPLY TIME



WOULD YOU PREFER A CHEMICAL OR MECHANICAL MEANS OF POTTING REMOVAL?

MECHANICAL - 15 CHEMICAL - 42

HEAT - 2

25%

71%

4%



からのできると、これでは、100mmのでは、100mm

HOW MANY SOLVENTS DO YOU CURRENTLY STOCK TO DEPOT COMPONENTS FOR REPAIR?

- TOLUENE
- DICHLOROMETHANE
- SISULFA-SOL
- TEF-SOL
- METHYLENE CHLORIDE
- ALCOHOL
- URESOLVE
- FREON
- SILICONE STRIPPER



WOULD A REDUCTION IN THE NUMBER OF SOLVENTS REQUIRED FOR DEPOTTING RESULT IN A COST SAVINGS FOR THE AIR FORCE?

YES · 15

8 · ON

62%

38%



SOMETIMES REQUIRE A PRIMER BEFORE POTTING. WOULD THE APPLICATION OF SILICONES AND POLYURETHANES A PRIMER BE ACCEPTABLE?

YES - 37 NO - 9

80% 20%





こうしょう いきかん はんしょう かんしょう かんしょう かんしょう かんしょう

NO OPINION SHOULD THESE MATERIALS BE USED FOR POTTING 25 25 38 31 2 22 ∞ YES 9 18 27 **POLYURETHANES COMPOUNDS? POLYSULFIDES** SILICONES **EPOXIES**



SUMMARY





EXISTING POTTING COMPOUNDS PREVENT ECONOMICAL REPAIR


FREQUENTLY APPLIED UNNECESSARILY POTTING COMPOUNDS ARE

POTTING COMPOUNDS SHOULD BE TRANSPARENT IF POSSIBLE




REMOVAL OF POTTING COMPOUNDS BY BY CHEMICAL MEANS IS PREFERRED

- **OVER ONE MILLION DOLLARS THROWN** AWAY ANNUALLY
- NO SOLUTION FOR PROBLEMS ON **EXISTING MODULES**



NEW PROCUREMENT SHOULD SPECIFY:

- CERTAIN TYPES OF POTTING COMPOUNDS TO BE USED
- TYPE OF REMOVAL TECHNIQUE AND MATERIAL
- POTTING BE USED ONLY WHEN ABSOLUTELY NECESSARY



K. Industry Response to Potting Compound Survey

John Ziegenhagen University of Dayton Research Institute 300 College Park Dayton, OH 45469 INDUSTRY RESPONSE TO

POTTING COMPOUND SURVEY

15 JUNE 1981

ELECTRONIC MODULE POTTING COMPOUND SURVEY

	6%	5%
1,000	61	64
TOTAL SENT OUT	TOTAL RETURNED	TOTAL COMPLETED

1. DO YOU CONSIDER THE USE OF POTTING COMPOUNDS ESSENTIAL IN THE PRODUCTION OF HIGH RELIABILITY ASSEMBLIES?

2 YES IN SOME CASES YES IN ALL CASES

12% 299 22%

POTTING COMPOUND IS OR IS NOT ESSENTIAL AND WHAT MATERIAL TYPE IT WILL BE. PLEASE STATE THE CRITERIA USED IN MAKING YOUR DECISION THAT A IF YOUR ANSWER TO QUESTION 1 IS "YES IN SOME CASES",

RITERIA

- IS VIBRATION OR SHOCK PROTECTION REQUIRED?
- ELIMINATE CONTAMINATION FROM DEBRIS
- EXTENT AND TYPE OF ENVIRONMENTAL PROTECTION
- HIGH VOLTAGE CONFINEMENT
- THERMAL TRANSFER REQUIREMENTS
- REPAIRABILITY REQUIREMENTS
- IMPEDANCE MATCHING

MATERIAL TYPE

- GROUNDBASE EPOXY AND AIRBORNE-SILICONE
- SILICONE FOR H.V., EPOXIES AND URETHANES FOR MECHANICAL STRENGTH

WHAT DO YOU CONSIDER TO BE IMPORTANT FUNCTIONS OF POTTING COMPOUNDS?

ENVIRONMENTAL PROTECTION

PROVIDE SUPPORT AND STRENGTH

PREVENT CORONA AND ARCING

DAMPEN AGAINST VIBRATION

MOISTURE BARRIER

MATCHING IMPEDANCE

TRANSFER HEAT

ADHES I ON

THERMAL EXPANSION OR CONTRACTION

COVER IDENTITY OF PARTS

TAMPER PROOF

EASE OF APPLICATION

REPAIRABILITY

LOW TEMPERATURE CURE

NO DEGRADATION IN HOT HUMID WEATHER

NO OUTGASSING

FUNGUS RESISTANCE

4. DO YOU USE POTTING COMPOUNDS ON ANY MODULES CURRENTLY IN PRODUCTION?

78%	16%
MILITARY APPLICATION	
YES	ON
	YES MILITARY APPLICATION 78%

5. ARE YOU PLANNING ON USING POTTING COMPOUNDS IN FUTURE

ELECT	ELECTRONIC SYSTEM DESIGNS?	% 517
YES		71%
N N		20%

6. IF YOU USE OR ARE CONSIDERING THE USE OF POTTING COMPOUNDS, PLEASE DESCRIBE THE POLYMERIC TYPES AND INDICATE IF THEY ARE TRANSPARENT OR OPAQUE.

A TOTAL OF THE PARTY OF THE PAR

- POLYURETHANE AND EPOXY SYSTEMS (BOTH CLEAR & OPAQUE)
- POLYSULFIDES (TRANSPARENT & OPAQUE)

EPOXIES, URETHANES AND SILICONES (TRANSPARENT & OPAQUE)

- POLYESTERS (TRANSPARENT & OPAQUE)
- EPOXIES (CLEAR, 3% & OPAQUE, 97%)

7. WHAT DO YOU CONSIDER TO BE THE THREE MOST IMPORTANT PROPERTIES THAT A POTTING COMPOUND MUST POSSESS?

- MUST BE READILY REPAIRABLE
- NON-TOXIC
- CHÉMICALLY INERT AND STABLE
- HIGH ELASTICITY
- VOID FREE
- RESIST ARCING/TRACKING IN H.V. APPLICATIONS
- GOOD ADHESION TO COMPONENTS OVER TEMPERATURE CYCLING
- GOOD ELECTRICAL INSULATION
- EASILY APPLIED AND REMOVED WITH MINIMAL RISK TO THE DEVICE
- FLAME RETARDANT
- LOW SHRINKAGE
- NON-CORROSIVE
- HIGH THERMAL CONDUCTIVITY
- LOW COEFFICIENT OF EXPANSION
- LONG POT LIFE
- ECONOMICAL
- ADHESION TO MYLAR AND ETCHED TEFLON
- FLOWS WELL BEFORE CURE
- CONSISTENTLY REPRODUCIBLE

8. IF A POTTED ELECTRONIC MODULE MUST BE REPAIRABLE WHICH POTTING COMPOUND WOULD YOU RECOMMEND?

LOW DUROMETER URETHANES AND SILICONES

CLEAR SILICOME ELASTOMER

EMMERSON CUMMING 2741 AND 2651

G.E. RTV-615

U.S. POLYMERIC V-370

M+T CHEMICALS URELANE 5754

SYLGARD

POLYSULFIDE

FLEXIBLE EPOXIES

ACRYLIC

ALIPHATIC AMINE CURED EPOXY

POLYURETHANE FOAM

WHAT ELECTRONIC MODULES PRESENTLY BEING POTTED COULD NOT BE POTTED IN REPAIRABLE POTTING MATERIALS? WHY? **о**

- NONE KNOWN
- MODULES WHOSE EXTERNAL CASE IS FORMED BY POTTING MATERIAL
- WIRE WOUND COMPONENTS WHERE WIRES MUST BE HELD RIGID
- OPERATIONAL AMPLIFIERS COEFFICIENT OF EXPANSION MISMATCHES AND THERMAL CONDUCTIVITY REQUIREMENTS
- SOME WOUND COMPONENTS BECAUSE OF SOLVENT EXPOSURES DURING CLEANING OPERATIONS
- COMBINATION OF REPAIRABILITY, HIGH TEMP RESISTANCE AND CHEMICAL COILS IN HIGH TEMPERATURE ENVIRONMENTS IMMERSED IN OILS - THE RESISTANCE DOES NOT EXIST
- HI-REL BECAUSE SILICONE IS HYGROSCOPIC
- LARGE MASS TRANSFORMER ASSEMBLIES
- HEAVY COMPONENTS WHICH REQUIRE GOOD VIBRATION DAMPENING
- LOW COST THROW AWAY ITEMS

CORDWOOD - EXPANSION COEFFICIENT WOULD CAUSE SOLDER JOINT FATIGUE

- CAPACITANCE CONTROLLED MODULES CHANGES IN THE POTTING DIELECTRIC STRENGTH WILL RENDER THE UNIT USELESS
- ALL PRESENT MODULES BECAUSE THERMAL EXPANSION/CONTRACTION, MOISTURE/SALT WATER PROTECTION, AND MECHANICAL STRUCTURE INADEQUATE
- TRANSFORMERS
- MODULES WITH HIGH THERMAL CONDUCTIVITY REQUIREMENTS

10. IN YOUR OPINION, WHAT ARE THE MAJOR PROBLEMS CURRENTLY ASSOCIATED **★WITH THE USE OF POTTING COMPOUNDS?**

- TOXICITY
- LONG CURE SCHEDULE
- TOO EXPENSIVE AND DIFFICULT TO CONTROL
- REPAIR NEARLY IMPOSSIBLE
- INSUFFICIENT DESIGNER KNOWLEDGE OF USE OF POTTING COMPOUNDS
- NONUNIFORM BATCH
- GOOD ADHESION (ESPECIALLY TO WIRE COATINGS)
- SHRINKAGE STRESSES
- MOISTURE PENETRATION THROUGH POTTING OR AROUND LEADS
- VOIDS OR BUBBLES
- PROPER CLEANING OF PARTS

10. CONTINUED

- STRESSES GENERATED BY THERMAL CYCLING
- MAGNETOSTRICTION AT LOW TEMPERATURES
- MOISTURE ENTRAPMENT AT POTTING
- ADDED WEIGHT
- COPPER CORROSION WITH EPOXIES
- REVERSION WITH POLYURETHANES
- REQUIRE HEAT CURE CYCLES

DO YOU PERFORM ANY REWORK AND REPAIR OF POTTED ELECTRONIC MODULES? 11.

CIRCLE ONE

37%

59%

REWORK/REPAIR PROCEDURES FOR THE TYPES OF POTTING COMPOUNDS 12. IF YOUR ANSWER TO QUESTION 11 IS "YES", BRIEFLY EXPLAIN YOUR ENCOUNTERED.

SILICONES - CUT AND DIG OUT

EPOXIES - CHEMICAL REMOVAL

URETHANES - CHEMICAL REMOVAL

MECHANICAL REMOVAL

HEATING AND CHIPPING

HOT KNIFE

X-RAY DETERMINES BEST EXCAVATION SITES

RECOMMENDED FOR REWORK/REPAIR IN THE FIELD (OR OPERATIONAL LEVEL)? 13. DO YOU BELIEVE THESE SAME PROCEDURES IN QUESTION 12 COULD BE MHY? CIRCLE ONE.

YES 27%

- THIS CAPABILITY IS NECESSARY
- ESPECIALLY FOR SILICONES
- ONLY IF MATERIAL EASILY APPLIED

N 0 45%

- LACK OF EQUIPMENT
- REQUIRES RIGID SAFETY CONTROL
- TOXIC SOLVENTS
- HIGH SKILL REQUIRED
- RELIABILITY LOW
- TOO COMPLICATED
- CLEANLINESS DIFFICULT TO ACHIEVE

OF POTTING COMPOUNDS AS THE ONLY METHOD OF SOLVING A PACKAGING PROBLEM? CAN YOU DESCRIBE ANY APPLICATION OR SITUATION THAT WOULD DEMAND THE USE 14.

The state of the s

HI TEMPERATURE THERMOCOUPLES

IN MANY CASES, POTTING IS MOST COST EFFECTIVE

FLEXIBLE PRINTED CIRCUITS

ACCELEROMETER

EXTREME VIBRATION

EXTREME HOSTILE ENVIRONMENTS

FLAT CABLE ASSEMBLIES

HIGH VOLTAGE APPLICATIONS (TRANSFORMERS)

CONNECTORS

HIGH SHOCK ENVIRONMENT (ELECTRONIC BOMB FUZES)

IMPEDANCE MATCHING

WHERE EQUIPMENT MAY BECOME SUBMERGED IN WATER

15. WHICH RESPONSIBILITY DO YOU HAVE RELATIVE TO POTTING COMPOUNDS AND ELECTRONIC MODULES? CIRCLE ONE. AND ELECTRONIC MODULES?

ADMINISTRATION	2%
PRODUCTION.	262
ENGINEERING	% 77%

COULD YOU MEET MILITARY OR HIGH RELIABILITY REQUIREMENTS IF THE USE OF POTTING COMPOUNDS WERE PROHIBITED OR ONLY SILICONES WERE PERMITTED WHERE POTTING WAS NECESSARY? EXPLAIN. 16.

The second secon

YES 41%

NO 59%

BARE UNITS COULD NOT SURVIVE

- SILICONES WORK IN SOME APPLICATIONS BUT MANY REQUIRE EPOXIES
- ADD FILLERS TO SILICONE
- RTV RESINS ARE MAJOR MATERIAL IN USE
- WOULD COST CONSIDERABLY MORE

- ENVIRONMENTAL HAZARDS

 SILICONES HAVE DEFICIENCIES DUE

 TO LARGE COEFFICIENT OF EXPANSION

 SILICONES EXHIBIT POOR RESISTANCE

 TO WATER VAPOR AND EPOXIES ARE

 NECESSARY
- SILICONES DO NOT PROVIDE TENSILE STRENGTH
- SILICONES UNSUITED TO 90% OF CURRENT MILITARY PRODUCTION
- SILICONES DO NOT HAVE GOOD ADHESION
- NOT RESISTANT TO CERTAIN FLUIDS

PLEASE MAKE ANY OTHER COMMENTS YOU FEEL ARE PERTINENT TO THE SUBJECT OF POTTING COMPOUNDS,

THE PARTY OF THE P

一丁丁 計 日日 多量の

- OPPOSED TO PARYLENE BECAUSE IMPOSSIBLE TO REWORK
- AVOID POTTING MATERIALS WITH COMPONENTS THAT PRECIPITATE
- AVOID HIGH CHLORINE CONTAINING RESINS
- SHELF LIFE SHOULD BE CHECKED
- PRIMERS ARE ESSENTIAL
- REPAIRABILITY IS A NICE CONCEPT AND SHOULD BE USED MORE BUT IT IS TOO RESTRICTIVE AND NOT PRACTICAL FOR TOTAL PRODUCTION APPLICATIONS
- MIL-SPEC MATERIALS SCARCE
- OUTGASSING OF MATERIAL IN SPACE APPLICATIONS
- POLYSULFIDES ARE ECONOMICAL AND HAVE GOOD ADHESION
- POLYURETHANES HAVE HIGH TEAR STRENGTH AND ARE IDEAL FOR GROUND SUPPORT EQUIPMENT
- TOO OFTEN THE ELECTRONICS DESIGN ENGINEER IGNORES THE EFFECTS OF POTTING HE WILL FINISH A MODULE THEN HAND IT OVER AND SAY "PLEASE POT"
- ENCAPSULATION IS A COST EFFECTIVE MEANS OF INSURING THAT THE FUNCTION OF THE DEVICE IS MAINTAINED FOR YEARS.

SECTION III

CONCLUSION

The Repairable Potting Materials Workshop indicated that the Air Force would definitely benefit from standardization of potting materials for electronic assemblies. Air Force personnel in our ALCs state that large dollar savings would result from the repair of many high cost electronic modules currently discarded as non-repairable. Industry reports that several potting technologies are available which provide repairability and maintain high reliability. The cost savings resulting from elimination of the many different potting materials and solvents by standardization would be an additional benefit for the Air Force.

It was generally assumed that a silicone material with appropriate fillers would best serve as a standard potting material. Everyone agreed that no one potting material is adequate for every application but a large spectrum of applications could utilize the repairable silicones as a standardized potting material for electronic modules.

